

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
MS	MS FIRST CAPITAL		Ref:	CS/FCI24110494/Knp3e2	
	16 RAFFLES QUAY		Date:	26/11/2024	
	#42-01 HONG LEON SINGAPORE 04858		Code:	FCI2	
4	SINGAPORE 04030	Policy Particulars :- THIRD PARTY CLAIM			
1.	Insured Veh.	SHA 2432Z	Veh. Inspected	SHC 5591S	
	Policy No.	-	Coverage	0	
	Claim No.	D24010222MFCT	Excess	\$0.00	
	Assign From	SWEE KEONG	Assign Date	25/11/2024	
2.	Assign From	Vehicle		23/11/2024	
۷.	Make & Model	TOYOTA PRIUS (A)	C.C	1798	
	Engine No.	2ZR2N53591	Year of Reg.	31/08/2022	
	Chassis No.	JTDKB3FU703095993	Colour	METALLIC PEARL WHITE / RED	
	Odometer	348241 KM	Steering	IN ORDER	
	Brakes	IN ORDER	General	GOOD	
	Modification(s)	RIMS: STANDARD ALLOY RIM	100110101		
3.					
0.		Size	Make	Balance (mm)	
	R/H Front Tyre	195/65R15	WANLI	6	
	L/H Front Tyre	195/65R15	WANLI	6	
	R/H Rear Tyre	195/65R15	WANLI	6	
	L/H Rear Tyre	195/65R15	WANLI	6	
4.	4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
DAMAGES SEE DETAILS.					
5.		General Information			
	Accident Date	19/11/2024	Inspection Date	22/11/2024	
	Survey held at	TRANS-CAB AUTO SERVICES PTE L NO.2 ANG MO KIO ST 63 SINGAPORE 569111	•		
5a.	a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b. Estimate Days of Repair					
• •					

ESTIMATED NORMAL PERIOD FOR REPAIR: 2 Working Days