

ASS. REC. BY:

REF:

CS/FCI 24110494/knp3

C

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

02 days

Res.: Yes or No

Lum Sum:

1B.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SHC 55915

Yr Regn:

08.22

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Prius

C.C

1798

Colour

MP White / Red

A/C:

Insured / Std / NI / NA

Sp. Reading

348241

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

JTDK B3FU 703095993

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size:

F:

195/65R15

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Wanli

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

19/11/24

D.O.I.

22/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

1

GOT BZ

26/11

@ 1719.53

Cobu

(Red, \$ 10451.47, 85%)

Date/Time, File Pass to?

☐

Prel. Report

1)

Date/Time, File Return to?

☐

Final Report

2)

Days Of Repair:

2

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

TOTAL

Add Fee:

☐

Site Insp (\$

☐

Interview (\$

☐

Tech Invs (\$

☐

Weekend (\$

Report Format :

Lump Sum / I.B.I: (\$

[> Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	878K

Vehicle Details

Vehicle No.:	SHC5591S
Vehicle to be Exported:	Yes
Intended Deregistration Date:	21 Nov 2024
Vehicle Make:	TOYOTA
Vehicle Model:	PRIUS 5DR HATCHBACK (AUTO)(2WD)
Primary Colour:	Red
Manufacturing Year:	2021
Engine No.:	2ZR2N53591
Chassis No.:	JTDKB3FU703095993
Maximum Power Output:	90.0 kW (120 bhp)
Open Market Value:	\$26,880.00
Original Registration Date:	31 Aug 2022
First Registration Date:	31 Aug 2022
Transfer Count:	0
Actual ARF Paid:	\$7,132.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	30 Aug 2030
PARF Rebate Amount:	\$5,349.00

Intended COE Rebate Details

COE Expiry Date:	30 Aug 2030
COE Category:	A - Car-Details at OneMotoring
COE Period(Years):	8
PQP Paid:	\$59,280.00
COE Rebate Amount:	\$42,786.00
Total Rebate Amount:	\$48,135.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be deregistered once the COE expires, or when it reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 21 Nov 2024

OK

Not Authorised
Presmy B4 paint

AAD2411-076

Q1719.53

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5591S

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 NOV 2021

SHC5591S

JTDKB3FU703095993

200303878K

TOYOTA

PRIUS GEN 4

19/11/24

SHIA24322 / FCI

31/8/2022

PART

LIST

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

\$	612.68	✓
\$	419.90	✓
\$	27.93	✓
\$	472.19	✓
\$	167.48	X
\$	167.48	X
\$	49.25	X
\$	49.25	X
\$	220.50	X
\$	304.92	X
\$	290.43	X
\$	159.39	X
\$	824.46	X
\$	1,443.86	X
\$	1,156.89	X
\$	68.88	X
\$	68.88	X
\$	90.30	X
TOTAL \$	6,594.67	
25% \$	1,648.67	
\$	4,946.00	

Special Nett

1SET PARKING AID

1SET REAR BUMPER CLIP

2 WINDSCREEN SEALANT

1 WINDSCREEN MOULDING

\$	700.00	X
\$	95.00	6050
\$	150.00	X
\$	200.00	X

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

AAD2411-**SHC5591S**

1 WINDSCREEN INNER SPONGE SEAL	\$	130.00	X
1 REAR TAILGATE STICKER "Trans-Cab"	\$	80.00	X
1 REAR TAILGATE STICKER "6555-3333"	\$	80.00	X
1 REAR NO. PLATE	\$	180.00	X
1 REAR BUMPER PROTECTOR	\$	180.00	300.00
2 SEAM SEALANT	\$	250.00	X
1SET REAR BUMPER RETAINER CLIP	\$	85.00	X
1 END PANEL TRIM CLIP	\$	65.00	X

TOTAL \$ 2,195.00**TOTAL PARTS \$ 7,141.00****LABOUR**

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 200.00

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 220.00

To reinstall rear bumper parking sensor.

\$ 170.00 50.00

To Check Electrical Lighting Concerned.

LKK Auto Consultants hence notify the Repairer of the following:

\$ 170.00 10.00

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$ 5,030.00

Acknowledged by Repairer

Signature:

Date:

Trans-cab Auto Services Pte Ltd

AAD2411-

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5591S

Over All Total	\$	12,171.00
----------------	----	-----------

(PART-BY-PART) Repair Days ~~8~~ DAYS

2 day,