

Not Authorized
Resurvey B4 paint

AAD2411-076

81719.53

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5591S

Vehicle No.:

Chassis No.:

Co UEN:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration:

22 NOV 2024

SHC5591S

JTDKB3FU703095993

200303878K

TOYOTA

PRIUS GEN 4

19/11/24

SHA2432Z/FcI.

31/8/2022

PART

- 1 COVER, REAR BUMPER
- 1 REINFORCEMENT SUB-ASSY, REAR BUMPER
- 1 COVER, REAR BUMPER, LOWER
- 1 GUARD, REAR BUMPER, CENTER
- 1 RETAINER, REAR BUMPER SIDE, LH
- 1 RETAINER, REAR BUMPER SIDE, RH
- 1 REFLECTOR ASSY, REFLEX, LH
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 COVER, FLOOR UNDER, NO.1 LH
- 1 COVER, FLOOR UNDER, NO.2 RH
- 1 COVER, REAR FLOOR CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 PANEL SUB-ASSY, BACK DOOR
- 1 GARNISH SUB-ASSY, BACK DOOR, OUTSIDE
- 1 PLATE, LUGGAGE COMPARTMENT DOOR NAME, NO.2
- 1 PLATE, BACK DOOR NAME, NO.1
- 1 ORNAMENT SUB-ASSY, BACK DOOR

LIST

DD/mg cm	612.68	
\$	Pr	419.90
\$	DD	27.93
\$	DD/LW	472.19
\$	Pr	167.48 X
\$	Pr	167.48 X
\$	Pr	49.25 X
\$	Pr	49.25 X
\$	Pr	220.50 X
\$	Pr	304.92 X
\$	Pr	290.43 X
\$	Pr	159.39 X
\$	Pr	824.46 X
\$	Pr	1,443.86 X
\$	Pr	1,156.89 X
\$	nn	68.88 X
\$	nn	68.88 X
\$	nn	90.30 X
TOTAL \$		6,594.67
25% \$		1,648.67
\$		4,946.00

Special Nett

- 1SET PARKING AID
- 1SET REAR BUMPER CLIP
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING

\$	Pr	700.00 X
\$	nn	95.00 60sn
\$	nn	150.00 X
\$	nn	200.00 X

AAD2411-

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHC5591S

- 1 WINDSCREEN INNER SPONGE SEAL
- 1 REAR TAILGATE STICKER "Trans-Cab"
- 1 REAR TAILGATE STICKER "6555-3333"
- 1 REAR NO. PLATE
- 1 REAR BUMPER PROTECTOR
- 2 SEAM SEALANT
- 1SET REAR BUMPER RETAINER CLIP
- 1 END PANEL TRIM CLIP

\$	nn	130.00	X
\$	nn	80.00	X
\$	nn	80.00	X
\$	nn	180.00	X
\$	nn	180.00	3am
\$	nn	250.00	X
\$	nn	85.00	X
\$	nn	65.00	X

TOTAL \$ 2,195.00

TOTAL PARTS \$ 7,141.00

LABOUR

To Remove And Refit Rear Big and Small W/Screen Glass To Facilitate Bodywork Repair.

\$ nn 300.00 X

To remove and refit interior fittings, trimings, garnish, fittings and other, to enable repair.

\$ nn 380.00 X

Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same

\$ 1,600.00 200l

To transfer of rear end panel fittings, attachment and perform water seepage test.

\$ nn 380.00 X

To transfer of Tailgate fittings, attachments and perform water seepage test.

\$ 180.00 X

To Rust-Proofing and apply undercoat Of The Affected Areas.

\$ 250.00 X

Putty And Spray Painting Of The Affected Portion.

\$ 1,600.00 220l

To reinstall rear bumper parking sensor.

\$ 170.00 50l

To Check Electrical Lighting Concerned.

\$ 170.00 10l

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

TOTAL \$ 5,030.00

Acknowledged by Repairer

Signature:

Date: