



ZOOM AUTOWERKS PTE LTD

130 Bedok Reservoir Road, Eunos Spring

#08-1339 Singapore 470130

email | zoomautowerks@gmail.com

D.O.A : 21/11/2024

OWNER : WANG XIPO

REG. NO. : SLM4959Y

MAKE/MODEL : AUDI A4

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged parts, for survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

not Authorized
du
merus

25/11/25

1/c \$4300

4 days

take photo after repair

ESTIMATED REPAIR COST FOR THE VEHICLE MENTIONED ABOVE

QTY	DESCRIPTION	AMOUNT(S\$)
<u>LIST ITEMS</u>		
1	Rear Boot lid	\$ 12 3,390.20 X
1	Rear boot lid Logo	\$ 11 212.00 X
1	Rear Left Tail lamp	\$ 11 1,050.00 X
1	Rear Right Tail Lamp	\$ 11 1,050.00 X
1	Rear bumper reflector	\$ 11 230.00 X
1	Rear bumper	2212.30 \$ del/cu 2,320.00
1	Rear End panel	1002.00 \$ 11 1,102.00
1	Rear end panel Top Trim	\$ su 355.00 X
1	Rear Reinforcement	905 \$ su 1,190.00
1	Rear Sensor	\$ su 667.20 X
		\$ 11,566.40
LESS 5% 102		\$ 578.32
		\$ 10,988.08
<u>SPECIAL NETT ITEMS</u>		
2	Front and Rear Number plate	\$ 11 150.00 X
1	Front and Rear Bumper Clips	\$ su 120.00 300 S/W
1	Rear Lower skirt	\$ del/cu 800.00 300 S/W
		\$ 1,070.00

S/N	LABOUR CHARGES	
1	To remove, replace damaged lamps & check up wiring	\$ 80.00 20
2	To remove & refit rear trims	\$ 11 120.00 X
3	To remove and refit Windscreen	\$ 11 180.00 X
4	To apply undercoating	\$ 150.00 30
5	Panel Beating	\$ 1,200.00 600
6	To re-spray the affected areas	\$ 1,500.00 800

P- 4119.3

102

3707.37

\$	3,230.00
----	----------

\$	15,288.08
----	-----------
