



Kah Motor Co. Sdn. Bhd.
(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

QUOTATION

GST Reg. No. : M200050223
Company Ref. No. : S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMN9585S
Chassis No : MRHGM6660LT000032
Model : CITY 1.5SV CVT 2020 (EURO 6)
Owner's Name : ANG CHUAN LEE
Ins Policy No. :
Date of Accident : 22/11/2024

Document No. : SQT24003167
Date : 27. Nov 2024
Customer No. : WZC008
Svc Advisor : MARSLER
Engine No : L15Z16930665
Date | Time : 27. Nov 2024 2:35:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 1

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount Incld GST
	TP DIRECT SETTLEMENT (J/NO:) (M) OWNER: ANG CHUAN LEE OWNER INSURER: INCOME INSURER ACC DATE: 22/11/2024 SURVEYED BY: DATE: REF NO: TP INSURER: CHINA TAIPING TP VEH: SJR997K						
68500-T9A-T30ZZ	LID COMPTRUNK R	1	554.10 X	25	415.57 X	37.40	452.97
68610-T9A-T00ZZ	HINGE COMPR.TRUNK Su	1	84.60 X	25	63.45 X	5.71	69.16
68660-T9A-T00ZZ	HINGE COMPL.TRUNK Su	1	84.60 X	25	63.45 X	5.71	69.16
74851-T2A-003	LOCK ASSYTRUNK Su	1	112.00 X	25	84.00 X	7.56	91.56
74865-T9A-T01	WEATHERSTRIPTRUNK LID n1	1	89.20 X	25	66.90 X	6.02	72.92
75701-T9C-000	EMBLEM H nu	1	13.70 /	25	10.27 /	0.92	11.19
91512-SR3-004	CLIP TUBULAR nu	2	2.50 /	25	3.75 /	0.34	4.09
75722-T9A-T10	EMBLEM, RR. CITY nu	1	14.10 /	25	10.57 /	0.95	11.52
75725-T9A-T00	EMBLEMRR.I-VTEC nu	1	14.70 /	25	11.02 /	0.99	12.01
66100-T9A-T50ZZ	PANEL COMPRR. Bcdh	1	403.70 X	25	302.77 /	27.25	330.02
84640-T9A-T01ZA	LINING ASSYRR.PANEL De	1	66.60 /	25	49.95 /	4.50	54.45
84521-T9A-T10	LID COMP SPARE TIRE n1	1	54.60 X	25	40.95 X	3.69	44.64
71501-T9A-T20ZZ	FACE, RR. BUMPER Ref to n	1	463.70 /	25	347.77 /	31.30	379.07
71505-T9D-K00	GARNISH, RR. BUMPER CENTER n1	1	26.50 X	25	19.87 X	1.79	21.66
71509-T9D-K00	GARNISH, L. RR. BUMPER SIDE n1	1	47.60 X	25	35.70 X	3.21	38.91
71593-T9A-J00	SPACER R.RR.BUMPER SIDE nu	1	11.50 /	25	8.62 /	0.78	9.40
71598-T9A-J00	SPACERL.RR.BUMPER SIDE nu	1	11.50 /	25	8.62 /	0.78	9.40
91505-TM8-003	CLIP,BUMPER nu	10	2.30 /	25	17.25 /	1.55	18.80
38387-TZ5-A01	ANTENNA ASSYL.F. n1	1	64.70 X	25	48.52 X	4.37	52.89

Printed on 27/11/2024 2:59:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.



QUOTATION

Kah Motor Co. Sdn. Bhd.

(A Member of Oriental Holdings Berhad)

Service and Body Repair

Tel: +65 6841 3838

Website: www.honda.com.sg

For 24-hours Roadside Assistance, Call 98203838

GST Reg. No. : M200050223

Company Ref. No. : S60FC1380G

Customer : CHINA TAIPING INSURANCE (S'PORE) PTE
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909
Registration No : SMN9585S
Chassis No : MRHGM6660LT000032
Model : CITY 1.5SV CVT 2020 (EURO 6)
Owner's Name : ANG CHUAN LEE
Ins Policy No. :
Date of Accident : 22/11/2024

Document No. : SQT24003167
Date : 27. Nov 2024
Customer No. : WZC008
Svc Advisor : MARSLER
Engine No : L15Z16930665
Date | Time : 27. Nov 2024 2:35:43 PM
Surveyor Name :
Survey Date :
Authorisation Date :

Page 2

Item	Description	Qty	Unit Price	Disc %	Amount	9% GST Amount	Amount incld GST
74940-TZ5-A01	BUZZER ASSYSMART 11	1	66.00	25	49.50	4.46	53.96
34155-T9A-T01	LIGHT ASSYL.LID 11	1	120.90	25	90.67	8.16	98.83
33550-T9A-T01	LIGHT ASSY,L.TAIL 11	1	235.90	25	176.92	15.92	192.84
NMRS-4P-TM3040L	4PCS ACT RR.SENSOR SVC	1	320.00		320.00	28.80	348.80
Sum Item					2246.09	202.16	2,448.25
BOSUN	SUNDRIES	1	100.00		100.00	9.00	109.00
BOJSE	BODY JOINT SEALANT.	1	100.00		100.00	9.00	109.00
BOBC	BODY UNDERSIDE COATING (N)	1	100.00		100.00	9.00	109.00
BP00R	APPLY BODY UNDERSIDE COATING (N).	1	250.00		250.00	22.50	272.50
BML02I	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER	1	200.00		200.00	18.00	218.00
BC012R	RESET VEHICLE SMART ENTRY SYSTEM	1	450.00		450.00	40.50	490.50
BKTRR	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID	1	650.00		650.00	58.50	708.50
BA02R	REMOVE & INSTALL REVERSE SENSORS	1	200.00		200.00	18.00	218.00
BMI03D	REMOVE & INSTALL REAR COMPARTMENT LININGS	1	650.00		650.00	58.50	708.50
BKRP21M	CUT OFF & RENEW RR PANEL. STRAIGHTEN RR FENDERS AN	1	3900.00		3900.00	351.00	4251.00
BP05R	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS. (5P)	1	3120.00		3120.00	280.80	3400.80
Sum Labor					9720.00	874.80	10,594.80

Survey By : Marcus Lee
Date & Time : 27/11/24 @ 2pm
Excess :
Status :
Signature :
Total Amount : 11,966.09 1,076.96 13,043.05
Total (Inclusive of GST) : 13,043.05

Printed on 27/11/2024 2:59:33 PM

This is a computer generated invoice. No signature is required.

Part prices are subjected to change without notice.

The above estimated cost of repair do not include any unforeseen damages.

GST Amount is calculated from individual line(s).

Charges of \$50.00 (excluding GST) will be applicable for the request of quotation above \$2000.00

However, if the repairs are subsequently done at Kah Motor Co. Sdn. Bhd, it will be refunded.

All quotations and prices are subjected to GST adjustment from 8% to 9% with effect from 1st Jan 2024.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: