

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT****Our File No:** CS/TMI24110499/EQP3M4**Date:** 05/12/2024**REFERENCE**

Handling Insurer:	Tokio Marine Insurance Singapore Ltd	Policy No:	MS008724		
<b>Claimant Vehicle No :</b>	SHA5845X	<b>Insured Vehicle No :</b>	SFL3411T		
Date of Loss:	21/11/2024	Nature of Claim:	TP	Claim No:	M2406817

**DESCRIPTION & IDENTIFICATION OF VEHICLE**

Reg No:	<b>SHA5845X</b>	Engine No:	G4LEKU404273
Make & Model:	HYUNDAI AE IONIQ HEV, 1.6 DCT (A)	Chassis No:	KMHC851CVKU141704
Reg. Date:	23/04/2019 (Man. Year: 2019)	Odometer:	739211 km
Colour:	Blue		
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	<b>Market Value/New Car Price</b>		

**CONDITION OF VEHICLE AT THE TIME OF SURVEY**

General Condition:	Fair	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	Good

**CONDITION OF TYRES**

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 5 mm	Rear Left Side:	West Lake 5 mm
Front Right Side:	West Lake 5 mm	Rear Right Side:	West Lake 5 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	3,212.96	80.00	3,132.96	97.51
Miscellaneous Items	12.00	12.00	0.00	0.00
Labour	1,600.00	960.00	640.00	40.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Gross Total (S\$)</b>	<b>4,824.96</b>	<b>1,052.00</b>	<b>3,772.96</b>	<b>78.20</b>
<b>+ GST 9.00/9.00% (S\$)</b>	434.25	94.68	339.57	78.20
<b>Nett Amount (S\$)</b>	<b>5,259.21</b>	<b>1,146.68</b>	<b>4,112.53</b>	<b>78.20</b>

**INSPECTION**

Date of Assignment:	22/11/2024	Present Location:	ComfortDelGro Engineering Pte Ltd (Loyang)
Date Inspected:	25/11/2024	Inspected At:	ComfortDelGro Engineering Pte Ltd (Loyang) 59 Loyang Drive Singapore 508969
Estimated Period of Repair:	2.0 days		

**Adjuster:** CHEN TSUE YEE**Manager:** SHIAU CHAN

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Dec 2024)
Parts:	143	HYUNDAI AE IONIQ HEV 1.6 DCT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA5845X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR DOOR RH	Repair	2,147.90 FL	*- FL
2	1		*RR FENDER RH	Repair	1,768.30 FL	*- FL
3	1		*REAR DOOR COMFORT LOGO LH	Necessary	80.00 F	*80.00 F
						F=Franchise part. L=ListItemDisc.
Sub Total (S\$)					3,996.20	80.00
- List Item Discount on L Items 20.00/20.00% (S\$)					783.24	0.00
Total Parts (S\$)					3,212.96	80.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No	Qty	Particulars	Repairer's	Amount
<u>Miscellaneous Items</u>				
1	1	OD/TP Case (Insurer)	12.00	12.00
Sub Total (\$\$)			12.00	12.00

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	800.00	380.00
2	SPRAY PAINTING CHARGE	New	600.00	560.00
3	TUFF KOTE	New	80.00	20.00
4	TRANSFER OF DOOR	New	120.00	0.00
Gross Labour Cost (\$\$)			1,600.00	960.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >