

**LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

**VEHICLE DAMAGE INSPECTION REPORT**ECICS Limited  
10 Eunos Road 8, #09-04A Singapore Post Centre  
Singapore 408600**Our File No:** CS/ICS24110500/UVP3E2**Date:** 13/01/2025REFERENCE

Insured/Claimant:	LOH CHOON KIAT	Policy No:	MPC23P00300000	
Date of Loss:	13/11/2024	Nature of Claim:	OD	Claim No: DMPC2401556H/ST

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	<b>SLU279K</b>		
Make & Model:	HYUNDAI ACCENT (RB), 1.4 CVT (A)	Engine No:	G4LCHU873544
Reg. Date:	21/11/2017 (Man. Year: 2017)	Chassis No:	KMHCU41BTJU388865
Colour:	Black	Odometer:	142153 km
Engine Capacity:	1368 cc		
Market Value/New Car Price:	S\$36,000.00		
Sum Insured (\$\$):	<b>Market Value/New Car Price</b>		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/55 R15	Rear Tyre Size:	195/55 R15
Front Left Side:	Giti 6 mm	Rear Left Side:	Giti 6 mm
Front Right Side:	Giti 6 mm	Rear Right Side:	Giti 6 mm

*The above values represent the remaining tyre treads depth*

<b>COST OF CLAIMS</b>	<b>Repairer's</b>	<b>Adjuster's</b>	<b>Difference</b>	<b>Diff %</b>
Parts	842.60	792.00	50.60	6.01
Miscellaneous Items	0.00	0.00	0.00	
Labour	790.00	350.00	440.00	55.70
Paintwork Labour	1,000.00	800.00	200.00	20.00
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (\$\$)</b>	<b>2,632.60</b>	<b>1,942.00</b>	<b>690.60</b>	<b>26.23</b>
<b>Approved Total (Overridden) (\$\$)</b>		<b>1,550.00</b>		
<b>(\$\$)</b>	2,632.60	1,550.00	1,082.60	41.12
<b>+ GST 9.00/9.00% (\$\$)</b>	236.93	139.50	97.43	41.12
<b>Nett Amount (\$\$)</b>	<b>2,869.53</b>	<b>1,689.50</b>	<b>1,180.03</b>	<b>41.12</b>

INSPECTION

Date of Assignment:	24/11/2024	Present Location:	Progressive Car Care Pte Ltd (HQ)
Date Inspected:	26/11/2024	Inspected At:	Progressive Car Care Pte Ltd (HQ) Blk 3022A Ubi Road 1, #01-45/46 Singapore 408716
Estimated Period of Repair:	4.0 days		

**Adjuster:** MARCUS CHUA**Manager:** VERON CHEN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 27 Nov 2024)
Parts:	143	HYUNDAI ACCENT (RB) 1.4 CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLU279K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1	NA	*REAR BUMPER (WCP)	Cut	480.00 F	*480.00 F
2	2	NA	*REAR BUMPER SIDE RETAINER - LH/RH (WCP)	Not Necessary	46.00 F	*- F
3	10	NA	*REAR BUMPER CLIPS (WCP)	Necessary	18.00 F	*18.00 F
4	1	NA	*REAR BUMPER REFLECTOR - LH (WCP)	Cracked	32.00 F	*32.00 F
5	1	NA	*TAILLAMP - LH (WCP)	Cracked	190.00 F	*190.00 F
					<hr/>	
					Sub Total (\$\$)	766.00 720.00
					+ Margin on L,N Items 10.00/10.00% (\$\$)	76.60 72.00
					<hr/>	
					Total Parts (\$\$)	842.60 792.00
					<hr/>	

F=Franchise part.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b><u>Paintwork Labour</u></b>				
1	TO RESPRAY PAINT ON ACCIDENT PORTIONS	New	1,000.00	800.00
<b><u>Labour Items</u></b>				
2	TO KNOCK OUT DENTS ON 2 DOORS LH; REAR FENDER LH, REMOVE, REPLACE ACCIDENT PORTIONS	New	770.00	330.00
3	TO CHECK WIRING	New	20.00	20.00
<b>Gross Labour Cost (\$\$)</b>			<b>1,790.00</b>	<b>1,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >