

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CS/MSG24110502/KQP3E2
Date: 11/12/2024**REFERENCE**

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	1003181939
Claimant Vehicle No :	SNP5025X	Insured Vehicle No :	SLZ7183E
Date of Loss:	21/11/2024	Nature of Claim:	TP
		Claim No:	381686

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SNP5025X	Engine No:	2ZR2X06756
Make & Model:	TOYOTA VOXY HYBRID, 1.8 X CVT (A)	Chassis No:	ZWR900116575
Reg. Date:	20/12/2023 (Man. Year: 2023)	Odometer:	97038 km
Colour:	Metallic Pearl White		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	225/50 R18	Rear Tyre Size:	225/50 R18
Front Left Side:	Yokohama 9 mm	Rear Left Side:	Yokohama 9 mm
Front Right Side:	Yokohama 9 mm	Rear Right Side:	Yokohama 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,035.37	3,219.98	815.39	20.21
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,820.00	1,690.00	1,130.00	40.07
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	6,855.37	4,909.98	1,945.39	28.38

INSPECTION

Date of Assignment:	25/11/2024	
Date Inspected:	25/11/2024	Inspected At: Rc Auto-160 Sin Ming (HQ) 160 SIN MING DRIVE, #06-20 SIN MING AUTOCITY Singapore 575722
Estimated Period of Repair:	5.0 days	

Adjuster: KENNETH KONG**Manager:** SHIAU CHAN*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

REPAIR DETAILS

Reference		
Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 09 Dec 2024)
Parts:	M1-MPV	TOYOTA VOXY HYBRID 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SNP5025X)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BOOTLID	Bent	2,773.70 FL	*1,985.91 FL
2	1		*REAR BUMPER	Buckled	1,092.80 FL	*1,092.80 FL
3	1		*REAR LAMP LOWER COVER	Missing	90.00 FL	*90.00 FL
4	1		*REAR LEFT HAND REFLECTOR	Cracked	165.10 FL	*165.10 FL
5	1		*REAR END PANEL ASSY	Bent	1,134.50 FL	*945.50 FL
6	4		*REAR BUMPER CLIP	Necessary	14.00 FL	*14.00 FL
7	2		*REAR BUMPER U SONIC RETAINER	Not Necessary	110.40 FL	*- FL
					Sub Total (\$\$)	5,380.50 4,293.31
					- List Item Discount on L Items 25.00/25.00% (\$\$)	1,345.13 1,073.33
					Total Parts (\$\$)	4,035.37 3,219.98

F=Franchise part. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO RESPRAY AFFECTED PORTION	New	700.00	600.00
2	TO REINSTATE REAR WINDSCREEN	New	180.00	120.00
3	TO RENEW ABOVE PARTS	New	1,200.00	600.00
4	ANTI RUST	New	60.00	60.00
5	TO TRANSFER REAR TAILGATE ACCESSORIES	New	80.00	60.00
6	TO CHECK WIRING	New	50.00	20.00
7	TO REMOVE REAR RADIO WOOFER AND SPEAKERS	New	250.00	80.00
8	TO REATTACHED SOUND PROOF	New	300.00	150.00
Gross Labour Cost (S\$)			2,820.00	1,690.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >