

# ESTIMATE

# RC AUTO

Not Authored  
Revised by pain  
84909.98

160 Sin Ming Drive #06-20 Sin Ming Autocity Singapore 575722

Tel : 97619383 Email: rcauto5555@gmail.com

Reg. No. 53199168K

5 days

SNP 5025 X

Date : 04.12.2024

Quantity	Description/Particular	Unit Price	Amount	
1 PC	REAR BOOTLID <i>1985.90</i>	<i>By</i> 2773	70	✓
1 PC	REAR BUMPER	<i>By</i> 1092	80	✓
1 PC	REAR LAMP LOWER COVER	<i>m1</i> 90	00	✓
1 PC	REAR LEFT HAND REFLECTOR	<i>CR</i> 165	10	✓
1 PC	REAR END PANEL ASSY <i>945.50</i>	<i>R</i> 1134	50	✓
4 PCS	REAR BUMPER <del>SIDE</del> CLIP@3.50	<i>m</i> 14	00	✓
2 PCS	REAR BUMPER U SONIC RETAINER @55.20	<i>m</i> 110	40	X
		TOTAL	5380	10
		LESS 25	4035	07
	TO RESPRAY AFFECTED PORTION		700	00 <i>600</i>
	TO REINSTATE REAR WINDSCREEN		180	00 <i>120</i>
	TO RENEW ABOVE PARTS		1200	00 <i>600</i>
	ANTI RUST		60	00 ✓
	TO TRANSFER REAR TAILGATE ACCESSORIES		80	00 <i>60</i>
	TO CHECK WIRING		50	00 <i>20</i>
	TO REMOVE REAR RADIO WOOFER AND SPEAKERS		250	00 <i>80</i>
	TO REATTACHED SOUND PROOF		300	00 <i>150</i>
	GRAND TOTAL		6855	07

Received the above goods in good order and condition for RC AUTO

Received by

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Authorised Signature