



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS SOMPO INSURANCE SINGAPORE PL	Ref:	CS/SMO24110504/Uvp3e2
50 RAFFLES PLACE #03-03	Date:	24/12/2024
SINGAPORE LAND TOWER SINGAPORE 048623	Code:	SMO

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FBL 2120L	Veh. Inspected	SGJ 7009U
Policy No.	-	Coverage	0
Claim No.	CMTD2403774/THE	Excess	\$0.00
Assign From	THELMA	Assign Date	25/11/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA ALTIS (A)	C.C	1598
Engine No.	1ZRY324176	Year of Reg.	15/02/2017
Chassis No.	MR053REH104555964	Colour	BLACK
Odometer	217554 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	MATRAX	215/45ZR17	6
L/H Front Tyre	MATRAX	215/45ZR17	6
R/H Rear Tyre	MATRAX	215/45ZR17	6
L/H Rear Tyre	MATRAX	215/45ZR17	6

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	19/11/2024	Inspection Date	26/11/2024
Survey held at	BLUWEL AUTOMOTIVE SERVICE PL BLK 1 KAKI BUKIT AVE 6 #01-28/53/55/56 (MAIN OFFICE) SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days