

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/TP/0887/2024/EQ
DATE : 27-Nov-24
WIP : 39697

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 28/11/2024

YOUR INSURED VEH NO : SGC 2388 U

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

OWNER'S NAME : MR RAJNISH KAPUR
ADDRESS : 19 KEW CRESCENT
SINGAPORE 466215

TELEPHONE : HP +65 91500455
TYPE OF CLAIM : THIRD PARTY CLAIM
POLICY NO : D24MTPV01006517
VEHICLE NO : **SNF 6639 X**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 14/6/2022
ENGINE NO : DKY 015447
CHASSIS NO : WAUZZZF21MN075807
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 25-Nov-24
PLACE OF ACCIDENT : ECP - NEAR BAYFRONT AVENUE EXIT. ECP OPPOSITE
MBS

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 6639 X

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID AND REAR LID KICK SENSOR.	S/N \$	360.00	
2	TO DISMANTLE AND RENEW REAR BUMPER. TO REPAIR REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,000.00	
3	TO RESPRAY REAR BUMPER AND REAR END PANELLING.	\$	1,500.00	
4	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	
TOTAL LABOUR CHARGES		:	\$ 3,152.00	

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 6639 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER	1	\$ 3,397.00	
2	REAR BUMPER SPOILER	1	\$ 1,107.00	
3	REAR BUMPER CHROME TRIM - LH / RH	2	\$ 614.00	
4	REAR BUMPER CHROME TRIM - CENTER	1	\$ 215.00	
5	REAR BUMPER SECURING STRIP	1	\$ 216.00	
6	REAR BOOT LID OPENING CONTROL UNIT	1	\$ 554.00	
7	REAR TAILGATE OPENING SENSOR LINE	1	\$ 244.00	
8	REAR AERIAL KEY ACCESS	1	\$ 129.00	
9	REAR TELEPHONE AERIAL - LH / RH	2	\$ 197.00	
10	REAR BUMPER REFLECTOR - LH / RH OUTER	2	\$ 98.00	
11	REAR BUMPER REFLECTOR - LH / RH INNER	2	\$ 82.00	
12	REAR PARKING AID SENSOR - INNER / OUTER	2	\$ 629.00	
13	REAR PARKING AID SEAL RING	4	\$ 11.00	
14	REAR BUMPER REINFORCEMENT BEAM	1	\$ 1,232.00	
15	REAR BUMPER SEAL - LH / RH	2	\$ 36.00	
16	REAR BUMPER HOLDING STRAP - CENTER	1	\$ 149.00	
17	REAR BUMPER GUIDE SECTION - CENTER	1	\$ 133.00	
18	REAR BUMPER GUIDE PROFILE - LH / RH	2	\$ 168.00	
19	REAR BUMPER GUIDE SECTION - LH / RH UPPER	2	\$ 114.00	
20	REAR BUMPER GUIDE SECTION - LH / RH LOWER	2	\$ 160.00	
21	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 9,885.00	
TOTAL LABOUR CHARGES		:	\$ 3,152.00	
GRAND TOTAL		:	\$ 13,037.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT