

Not Authored
11/11/2024

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SMZ6598L

LAD2410-005

Vehicle No.:

Chassis No.:

Co UEN.:

Vehicle Make:

Vehicle Model:

Date of Accident:

Third Party Insurer:

Date of Registration:

SMZ6598L

JTDKB3FU303092914

200303878K

TOYOTA

PRIUS GEN 4

3/10/2024

SMZ9059G/AUTO GEN

11/5/2021

25 NOV 2024

PART

LIST

- 1 COVER, REAR BUMPER
- 1 GUARD, REAR BUMPER, CENTER
- 1 REFLECTOR ASSY, REFLEX, RH
- 1 SEAL, REAR BUMPER SIDE, RH
- 1 REAR BUMPER SIDE RETAINER RH
- 1 COVER, FLOOR UNDER, RH
- 1 COVER, FLOOR UNDER, NO.2 CTR
- 1 COVER, DECK TRIM, REAR
- 1 PANEL SUB-ASSY, BODY LOWER BACK
- 1 LENS & BODY, REAR COMBINATION LAMP, RH
- 1 LENS & BODY, REAR COMBINATION LAMP, NO.2 RH
- 1 COVER, REAR COMBINATION LAMP, RH
- 1 PANEL SUB-ASSY, QUARTER, RH
- 1 LINER, REAR WHEEL HOUSE, RH

Bar / cm	612.68	✓
\$	472.19	X
\$	49.25	X
\$	149.21	X
\$	167.48	✓
\$	220.50	X
\$	304.92	X
\$	159.39	X
\$	824.46	X
\$	428.19	X
\$	329.49	X
\$	88.41	X
\$	1,099.46	X
\$	176.09	X

TOTAL \$ **5,081.72**
25% \$ **1,270.43**
\$ 3,811.29

SPECIAL NETT

- 1SET PARKING AID
- 1 REAR BUMPER CLIP
- 1 REAR LH BUMPER RETAINER CLIP
- 1 REAR RH BUMPER RETAINER CLIP
- 1 END PANEL INNER TRIM CLIP
- 1 REAR BUMPER PROTECTOR
- 2 WINDSCREEN SEALANT
- 1 WINDSCREEN MOULDING
- 1 WINDSCREEN INNER SPONGE SEAL

\$	700.00	X
\$	65.00	65.00
\$	65.00	X
\$	65.00	X
\$	60.00	X
\$	180.00	X
\$	150.00	X
\$	200.00	X
\$	130.00	X
TOTAL \$	1,615.00	

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No Fax No. : 62571330

CO./ GST Reg. No. 201019626G

SMZ6598L**LAD2410-005****TOTAL PARTS** \$ 5,426.29**LABOUR**

To rust-proofing of the affected areas.	\$	nn	600.00	X
Putty and spray painting of the affected portion.	\$		1,200.00	4401
Panel beating, knocking and straightening the necessary portion, remove and renewal of parts, adjust and realign the same	\$		2,000.00	4001
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To remove and refit interior fittings, trimmings, garnish, fittings and other, to enable repair.	\$		380.00	801
To transfer of tailgate fittings and conduct water seepage test.	\$	nn	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	501
To check steering geometry and computer wheel alignment	\$	nn	220.00	X
To Transfer Of Fender Fittings, Attachments And Perform Water Seepage Test.	\$	nn	170.00	X

TOTAL \$ 5,080.00**OVERALL TOTAL** \$ 10,506.29*3 days*

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: