

MODERN AUTOMOTIVE PTE LTD
BLK 3023A UBI ROAD 1 # 01-61
SINGAPORE 408717

Tel : 6748 4422 / 6745 4422 Fax : 6747- 6720 REG NO 200501102H

Daphne

India International Insurance Pte Ltd

64, Cecil Street #04-05
IOB Building
Singapore 049711
Tel : 6347 - 6100
Fax : 6224 - 4174

Quotation

DATE : 03.12.2024
VEH NO : SJS1273D
MODEL : Toyota Previa
D O A : 22.11.2024
YR REF : SNH849K

Attn : Motor Claim Dept (Pls arrange vehicle surveyor & check liability)

RE : ESTIMATE FOR ACCIDENT REPAIR SJS1273D (TOYOTA PREVIA)

<u>Item</u>	<u>Description</u>	<u>Qty</u>	<u>Amt</u>
NO	LIST ITEMS		
1	Rear Bumper <i>Debond</i>	1	917.90 ✓
2	Rear Bumper Side Holder - LH & RH <i>x 100 per</i>	2	120.40 X
3	Rear Bumper Tow Cover <i>x 100 per</i>	2	56.20 X
4	Rear Bumper Reflector - LH & RH <i>LH Cracked</i>	2	121.60 <i>60.60</i>
5	Rear Bumper Sensor <i>Damaged</i>	2	710.80 ✓
6	Rear Bumper Sensor Holder <i>in</i>	2	50.20 ✓
7	Rear End Panel <i>Dented</i>	1	1,151.30 ✓
8	Rear End Panel Top Garnish <i>Debond</i>	1	336.80 ✓
9	Rear End Panel Lower Garnish	1	259.80 ✓
10	Rear End Panel Antenna Sensor <i>x 100 per</i>	1	200.60 X
11	Tail Lamp - LH & RH <i>x 100 per</i>	2	1,508.20 +
12	Tailgate <i>Dented</i>	1	2,671.70 ✓
13	Tailgate Lock <i>Damaged</i>	1	495.50 ✓
14	Tailgate Weatherstripe <i>Damaged</i>	1	397.40 ✓
15	Tailgate Inner Trim Board <i>x 100 per</i>	1	694.50 +
16	Tailgate Outer Chrome Moulding <i>x 100 per</i>	1	312.40 +
17	Tailgate Glass Moulding <i>x 100 per</i>	1	185.90 ✓
18	Toyota Logo	1	75.80 ✓
19	Toyota Wording <i>in</i>	1	60.40 ✓
20	Previa Wording	1	57.90 ✓
21	Spare Tyre Panel Top Board <i>in</i>	1	1,266.90 X
22	Rear Fender Inner Trim Board <i>in</i>	2	2,514.40 X
			\$ 14,166.60
Less 25%			(3,541.65)
			\$ 10,624.95

S/NET ITEMS

RE : ESTIMATE FOR ACCIDENT REPAIR SJS1273D (TOYOTA PREVIA)

1	Rear Bumper Clips	1 set	\$	30.00	✓
2	Rear End Panel Top Garnish Clips	1 set	\$	20.00	✓
3	Rear End Panel Lower Garnish Clips	1 set	\$	20.00	✓
4	Rear End Panel Sealant	1 set	\$	60.00	✓
5	Tailgate Inner Trim Board Clips	1 set	\$	30.00	x
6	Tailgate Glass Sealant	1 set	\$	60.00	✓
7	Rear Fender Inner Trim Board Clips	2 sets	\$	60.00	x
				<u>\$</u>	
				280.00	

Total Parts

\$ 10,904.95

LABOUR CHARGE

1	To knocking & pull out rear portion & renew above parts	\$	1,200.00	80
2	To putty & spray up paint works	\$	1,000.00	80
3	To check wiring	\$	50.00	30
4	To check wiring	\$	50.00	x
5	To apply tuff coat	\$	150.00	80
6	To remove reverse sensor	\$	100.00	50
7	To remove rear camera	\$	100.00	50
8	To remove upholstery	\$	150.00	80
9	To transfer tailgate fittings	\$	150.00	80
10	To remove tailgate glass	\$	180.00	120

Total Labour

\$ 3,130.00

Grand Total

\$ 14,034.95

GST Will be reflected in the final bills

NOTE : -

PLEASE INFORM US WITHIN 14 DAYS, FROM THE DATE OF THIS LETTER, IN THE EVENT THAT THE OWNER/DRIVER IS IN BREACH OF ITS POLICY WITH YOUR COMPANY, FAILING WHICH WE SHALL HOLD YOUR COMPANY LIABLE FOR ALL COSTS OF REPAIRS, LOSS OF USE AND STORAGE.

LKR Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to change
- This party survey is on a "Without Prejudice" basis
- Supplemental charges may be incurred
- All work is subject to final approval from the customer and

Acknowledged by Repairer
Signature:
Date:

total: 7854
W/S: 6250

06 Days.