

DICKSON AUTO CARE CENTRE PTE LTD

29 UBI ROAD 4, DICKSON AUTO CENTRE SINGAPORE 408619

TEL: 6668 1122 | **FAX:** 6668 1123

QUOTATION

DATE: 22/11/2024

REF: SD0B24AL0001
VEHICLE NO: SMZ1623E
MAKE: MERCEDES

MODEL: C180
PREPARED BY: XIANG

QUOTATION FOR

NAME: MS First Capital Insurance Ltd
COMPANY NAME: MS First Capital Insurance Ltd
STREET ADDRESS: 6 Raffles Quay, #21-00
POSTAL CODE: Singapore 048580
PHONE: 6222 2311

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT	DISC	AMOUNT	
	LABOUR							
1	TO REMOVE & REPLACE BUMPER FRONT, FENDER LINER FRONT LH, DAYTIME RUN LAMP FRONT LH, ENGINE UNDERCOVER CENTRE, BUMPER FRONT UNDERCOVER & ALL ACCIDENT DAMAGE BODY PARTS & ALL AREAS AFFECTED BY THE ACCIDENT	1		\$500.00	\$ 500.00		\$ 500.0	
2	TO SPRAY BUMPER FRONT	1		\$300.00	\$ 300.00		\$ 300.0	
3	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING	1		\$100.00	\$ 100.00		\$ 100.0	
4	TO PROGRAMME AFTER THE ACCIDENT REPAIR WORKS	1		\$150.00	\$ 150.00		\$ 150.0	
5	TO CARRY OUT BODY CAVITY PRESERVATION	1		\$150.00	\$ 150.00		\$ 150.0	
6	SUNDRIES	1		\$100.00	\$ 100.00		\$ 100.0	
	PARTS							
1	BUMPER FRONT	1		\$1,022.00	\$ 1,022.00		\$ 1,022.0	
2	BUMPER CLIPS	10		\$7.00	\$ 70.00		\$ 70.0	
3	FENDER LINER FRONT LH	1		\$196.00	\$ 196.00		\$ 196.0	
4	FENDER LINER CLIPS	10		\$7.00	\$ 70.00		\$ 70.0	
5	DAYTIME RUN LAMP FRONT LH	1		\$406.00	\$ 406.00		\$ 406.0	
6	DAYTIME RUN LAMP TRIM FRONT LH [CHROME]	1		\$91.00	\$ 91.00		\$ 91.0	

S/N	DESCRIPTION	QTY	UOM	UNIT PRICE	AMOUNT BEFORE DISCOUNT		DISC	AMOUNT	
7	ENGINE UNDERCOVER CENTRE	1		\$1,239.00	\$	1,239.00		\$	1,239.00
8	BUMPER FRONT UNDERCOVER	1		\$154.00	\$	154.00		\$	154.00
9	SENSOR BRACKET FRONT [SET]	1		\$200.00	\$	200.00		\$	200.00
				SUBTOTAL	\$	4,748.00	SUBTOTAL	\$	4,748.00
REMARKS:				GST 9%	\$	427.32	GST 9%	\$	427.32
				TOTAL	\$	5,175.32	TOTAL	\$	5,175.32

I AGREE TO THE REMARKS AND PRICE AS LISTED ABOVE.

FOR DICKSON AUTO CARE CENTRE PTE LTD

UEN: 201921 MOUK

(CUSTOMER'S SIGNATURE AND COMPANY STAMP)

(AUTHORISED SIGNATURE)