



Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/11/2024

User ID : PohSuan

Section A - Accident Details	
Registration Number	SHB5492A
Case Reference Number	TAX/11/24/2082
Registration Date	19/Dec/2017
Company Type	Strides Premier Taxi Pte Ltd
Make	TOYOTA
Model	PRIUS4
Name of Driver	TAN HOCK CHUAN
Type of Accident	Side Swipe
Accident Date and Time	23/Nov/2024 4:55 PM
Accident Reported Date and Time	25/Nov/2024 8:34 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	ACGJ24110090
Special Instruction to ARC,if any	TP/RIGHT REAR PORTION
Prepared Date and Time	25/Nov/2024 10:24 AM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates		
Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$676.00	\$50.00
Total Spray Cost	\$1,196.00	\$80.00
Total Spare Part Cost	\$2,784.72	\$0.00
Total Other Cost	\$1,090.00	\$100.00
TOTAL COST	\$5,746.72	\$230.00 (P/P)
Lump Sum Total	\$5,750.00	\$0.00
Number of Repair Days	5.0	2.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN (LKK) / AIG
ARC / Surveyor Sign Off Date	25/11/2024 6:51 PM	25/11/2024 5:56 PM
Signature		
Remarks	Expected length of repair (days) = 2 days Expected release date of vehicle after repair (Subject to approval from FM and without Supplementary) = 29-11-2024 L/S REPAIR / AFTER PAINT PHOTO , FOR CHECK ITEM and REPLACE ITEM PLEASE CALL SURVEYOR STEVE CHEN (LKK) / HP : 010-9429 541 / Email : stevechen@lkkauto.com	

Section C - Quotation and Accident Invoice Details			
Quotation Number	E24110198	Invoice Number	
Quotation Date	25/11/2024	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates		
Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION RH	\$676.00	\$50.00
Total Labour	\$676.00	\$50.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY REAR FENDER RH	\$378.00	\$0.00
TO RESPRAY REAR BUMPER	\$378.00	\$0.00
TO RESPRAY RIM	\$220.00	\$80.00
TO RESPRAY FILLER RR BUMPER RH	\$220.00	\$0.00
Total Spray Painting & Panel Beating	\$1,196.00	\$80.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$0.00
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$80.00
TO REMOVE AND REFIT TYRE	\$120.00	\$20.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE AND REFIX UNDERCARRIAGE	\$350.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$0.00
Total Other Costs	\$1,090.00	\$100.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		5246247020	PAD, RR BUMPER, RH & LH , 2	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5246247010	PAD, RR BUMPER, RH & LH , 3	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5216116010	CLIPS PIECE, RR BUMPER	0.00	\$4.80	0.00	\$0.00	Replace	Not Given
		5246247030	PAD, RR BUMPER, RH & LH , 1	0.00	\$4.30	0.00	\$0.00	Replace	Not Given
		5215947913	COVER, RR BUMPER ASSY	0.00	\$478.90	0.00	\$0.00	Replace	Not Given
		4245076020	HUB & BEARING ASSY WITH SPEED SENSOR , REAR	0.00	\$644.10	0.00	\$0.00	Replace	Not Given

X
X
X
X
X
X
X

Strides Premier Accident Vehicle Repair Estimates

Strides Premier Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 29/11/2024
User ID : PohSuan

		4261147450	WHEEL, DISC	1.00	\$2,036.30	100.00	\$0.00	Replace	Repair
		6160147150	PANEL SUB-ASSY, FENDER REAR RH	0.00	\$943.10	0.00	\$0.00	Replace	Not Given
		5256547900	FILLER, RR BUMPER , RH	0.00	\$168.60	0.00	\$0.00	Replace	Not Given
		5257547040	RETAINER, RR BUMPER, RH	0.00	\$127.40	0.00	\$0.00	Replace	Not Given
			TYRE	0.00	\$126.74	0.00	\$0.00	Replace	Not Given
Total					\$4,542.84		\$0.00		

R
X
X
X
X

Added Spare Parts / Material Usage After Surveyor Signed off									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

0.00
+ 50.00
+ 180.00

230.00