

REPAIR ESTIMATE

Claim Type: Third Party Claim Date : 10 Feb 2025
 Attn: India International Insurance Pte Ltd Vehicle Num : SLB6349C
 Motor Claims Department Make/Model : HONDA FIT 1.3G
 Owner: SIOW KEE LIN Chassis # : GK31200814
 DOA: 31 Oct 2024 Engine # : L13B1300821
 Yr. Of Manu : 2015/16

No. Description	Qty	U/P	Amt
<u>Section: LIST ITEMS</u>			
1 Front Bumper	1 S\$	620.20 S\$	620.20 +
2 Front Bumper Retainer LH/RH	2 S\$	28.50 S\$	57.00 +
3 Front LH Headlamp	1 S\$	1250.70 S\$	1,250.70 +
4 Front LH Headlamp Bracket	1 S\$	129.80 S\$	129.80 +
5 Front LH Fender	1 S\$	580.90 S\$	580.90 +
6 Front LH Fender Inner Shiled	1 S\$	257.90 S\$	257.90 +
7 Front Door LH <i>Riv</i>	1 S\$	560.80 S\$	560.80 +
8 Rear Bumper <i>Delat</i>	1 S\$	692.70 S\$	692.70 ✓
9 Rear Bumper Retainer LH/RH <i>new</i>	2 S\$	28.50 S\$	57.00 +
10 Rear LH Fender <i>Repair</i>	1 S\$	697.20 S\$	697.20 +
11 Rear Fender Inner Shield LH <i>3 new</i>	1 S\$	191.00 S\$	191.00 +
12 Rear Fender Inner Air Duct LH <i>new</i>	1 S\$	38.90 S\$	38.90 +
13 Rear Door LH <i>Delat</i>	1 S\$	620.90 S\$	620.90 ✓
14 Roacker Panel LH <i>Revised</i>	1 S\$	489.80 S\$	489.80 ✓
15 Rear Wheel Bearing and Hun LH <i>new</i>	1 S\$	340.70 S\$	340.70 +
16 Rear Axle <i>new</i>	1 S\$	1052.90 S\$	1,052.90 +
		Amt S\$	7,638.40
	DISCOUNT:	20% S\$	1,527.68
		Subtotal S\$	6,110.72

No. Description	Qty	U/P	Amt
<u>Section: Special Nett</u>			
17 Front Bumper Clips <i>new</i>	1 S\$	80 S\$	80.00 +
18 Rear Bumper Clips <i>new</i>	1 S\$	80 S\$	80.00 30
19 Front Fender inner Shiled Clips <i>3 new</i>	1 S\$	80 S\$	80.00 +
20 Rear Fender Ineer Shiled Clips	1 S\$	80 S\$	80.00 +
21 Rear RIM LH <i>cut</i>	1 S\$	280 S\$	280.00 ✓
22 Rear Tyre LH <i>new</i>	1 S\$	250 S\$	250.00 +
		Amt S\$	850.00

Continue on next page...

No.	Description	Amt
<u>Section: LABOUR</u>		
23	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.	1,500.00 S\$ 800
24	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT	1,500.00 S\$ 800
25	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS.	150.00 30 S\$
26	APPLY RUST COATING CHEMICAL ON AFFECTED AND CONSISTENT AREAS AND PANELS	180.00 60 S\$
27	REMOVE, REINSTALL, AND REPLACE FRONT AND REAR DOOR INNER MECHANISM TO ASSIST REPAIR	150.00 60 S\$
28	REMOVE, REINSTALL, AND REPLACE REAR UNDERCARRIAGE PARTS TO ASSIST REPAIR	250.00 + S\$
Amt S\$		3,730.00



Joo Hak Kee Auto Pte. Ltd.

LIST ITEMS Subtotal S\$	6,110.72
SPECIAL NETT ITEMS Subtotal S\$	
LABOUR Subtotal S\$	3,730.00
Total S\$	9,840.72

Adrian Lj
 2/5 18/02/25
 06 Days
 96893735

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: