



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO FZ 6789K

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	EXHAUST PIPE PROTECTOR	CUT	\$89.00	\$89.00
1	RIGHT SIDE FRONT PANEL	CUT	\$105.00	\$105.00
1	FRONT MUG GUARD	CUT	\$98.00	\$98.00
1	RIGHT SIDE SIGNAL LIGHT	CUT	\$75.00	\$75.00
1	RIGHT SIDE LEVER	NOT NECESSARY	\$60.00	\$0.00
1	OUTER PANEL	CUT	\$198.00	\$198.00
1	LOWER PANEL	CUT	\$95.00	\$95.00
1	RADIATOR PANEL	CUT	\$55.00	\$55.00
	<b>LESS 0.00 / 10.00% DISCOUNT</b>		\$0.00	(\$71.50)
			<b>\$775.00</b>	<b>\$643.50</b>

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	LABOUR CHARGE		\$150.00	\$120.00
			\$150.00	\$120.00

<b>GRAND TOTAL</b>			<b>\$925.00</b>	<b>\$763.50</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>\$763.50</b>

Report Ref No: CS/FCI24110515/Evp3m4

**CTY**

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of repositibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.