



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD

300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

INV No. AC2502941

INV Date 14/05/2025

Reference CD/LPC24110517/Ama3q2

Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. SLS 303J
Insured Veh. GBH 6632X
Claim No. 24/24/24/VC05/030174
Policy No. Z24VC05000002
Accident Date 11/11/2024
Inspection Date 27/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555			Ref: CD/LPC24110517/Ama3q2(N)	
			Date: 14/05/2025	
			Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GBH 6632X	Veh. Inspected	SLS 303J
	Policy No.	Z24VC05000002	Coverage (\$)	0.00
	Claim No.	24/24/24/VC05/030174	Excess (\$)	0.00
	Assign From	ENG HUEY NI	Assign Date	27/11/2024
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA HARRIER	c.c	1998
	Engine No.	HIDDEN	Year of Reg.	2017
	Chassis No.	JTEKB3GH90J000228	Colour	BLACK
	Odometer	109940 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Front Tyre	235/55 R18	YOKOHAMA	6 mm
	R/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
	L/H Rear Tyre	235/55 R18	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	11/11/2024	Inspection Date	27/11/2024
	Survey held at	MG SOLUTION PTE LTD 23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		3 Working Days	



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLS 303J

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	<u>REPLACEMENT OF PARTS</u>	DENTED		
	REAR DOOR LH		1,850.00	1,550.00
	LESS 25% DISCOUNT		-462.50	-387.50
			1,387.50	1,162.50
	<u>LABOUR</u>	NOT NECESSARY		
	PANEL BEATING ,REMOVAL AND REPLACING PARTS.		400.00	200.00
	TO SPRAY PAINT AFFECTED AREA.		400.00	200.00
	TUFF COAT.		200.00	-
	WIRING CHECK.		80.00	-
	TRANSFER REAR DOOR MECHANISM .		100.00	60.00
			1,180.00	460.00
GRAND TOTAL			2,567.50	1,622.50
RECOMMENDED COST OF REPAIRS				1,622.50

Report Ref No. CD/LPC24110517/Ama3q2(N)


ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.





LKK Auto Consultants Pte Ltd



51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315




Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 2 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J



PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 4 of 4)

PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315




Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J



PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 2 of 2)

PHOTOGRAPHS FOR VEHICLE NO. : SLS 303J

