



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MS INCOME INSURANCE LTD		Ref:	CS3/INC24110519/Aqh3m4	
75 BRAS BASAH ROAD		Date:	06/12/2024	
INCOME CENTRE SINGAPORE 189557		Code:	INC	
1. Policy Particulars :- PRE-REPAIR SURVEY				
Insured Veh.	SKN 7177Z	Veh. Inspected	SKH 6126J	
Policy No.	-	Coverage	0	
Claim No.	MT/1303885-002	Excess	\$0.00	
Assign From	JEFF LIN	Assign Date	13/11/2024	
2. Vehicle Details				
Make & Model	BMW 328i	C.C	1997	
Engine No.	A1790134N20B20A	Year of Reg.	28/12/2012	
Chassis No.	WBA3A52040F254129	Colour	BLACK	
Odometer	126848 KM	Steering	IN ORDER	
Brakes	IN ORDER	General	GOOD	
Modification(s)	RIMS: SPORTS RIM			
3. Conditions of Tyres				
	Size	Make	Balance (mm)	
R/H Front Tyre	225/45R18	PIRELLI	6	
L/H Front Tyre	225/45R18	PIRELLI	6	
R/H Rear Tyre	225/45R18	PIRELLI	6	
L/H Rear Tyre	225/45R18	PIRELLI	6	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.				
5. General Information				
Accident Date	11/11/2024	Inspection Date	14/11/2024 (15:24)	
Survey held at	RYDER AUTO PTE LTD 2 KAKI BUKIT AVE 2 #02-19/22 KAKI BUKIT AUTOHUB SINGAPORE 417921			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				

LWP

ADRIAN LING WAI PING

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.