

CHOON HOCK MOTOR TRADING CO

25 November 2024

Not Authorized
 61 Lp & 410dp
 Resurvey After Paint
 4 days

ESTIMATE REPAIR BILL ON SH2264A TOYOTA COROLLA AXIO 1.5X

1 pce rear boot	R1	\$ 850.20	✓
1 pce rear boot inner garnish	brs	\$ 229.20	✓
2 pcs rear boot hinges	n	\$ 273.60	X
1 pce rear lock	del	\$ 94.30	✓
1 pce rear boot outer holder	wap	\$ 300.80	✓
1 pce rear boot logo	m	\$ 50.30	✓
2 pcs rear lamp	cm	\$ 1,198.40	✓
2 pcs rear lamp inner panel	cl/R1	\$ 267.60	2x
1 pce rear bumper	R1	\$ 530.50	✓
2 pcs rear bumper side retainer	DT	\$ 184.60	✓
1 pce rear panel	R1	\$ 602.20	✓
1 pce rear panel garnish	del	\$ 218.90	✓
1 pce rear boot rubber	DIS/DEL	\$ 185.20	508.00 91.60.00
1 pce rear exhaust pipe	n	\$ 372.30	X
2 pcs rear exhaust pipe rubber	Sn	\$ 62.60	X
		\$ 5,420.70	
	less 20%	\$ 1,084.15	
		\$ 4,336.55	

S/NETT

1 pce rear sensor	del	\$ 220.00	200.00
Towing	(Bill)	\$ 180.00	700
Remove and refit sensor		\$ 100.00	500
Remove and refit exhaust pipe	nn	\$ 180.00	X
Wiring		\$ 100.00	200
Panel beating		\$ 1,300.00	600
Spray painting		\$ 1,500.00	800
Rustproof		\$ 150.00	60
Total amount :		\$ 8,066.55	NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- Any alteration/modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Mailing address: 28 Surrey Road #18-03 Singapore 6307762 Reg No: 30568200L
 Tel: (65) 64530778 Email: choonhockmotor@gmail.com

Acknowledged by Repairer
 Signature:
 Date: