

ASS. REC. BY:

REF:

C9/105 24110520/Kap3

C

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

06/25

Person Contacted:

Vehicle: IN / OUT

Veh No:

S/H 2264A

Yr Regn:

06, 17

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toy Axio

C.C.

1496

Colour

Yellow/Black

A/C:

Insured / Std / NI / NA

Sp. Reading

243453

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

NRE161

0022545

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NI / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

185/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI / TOYO / YOKO or

Falken

Front

Rear

R/Bal.

8

mm

R/Bal.

8

mm

L/Bal.

8

mm

L/Bal.

8

mm

D.O.A.

22/11/24

D.O.I.

26/11/2024

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

28/11 11Pm @ 4100h Cabnet CRed to 3966.55, 49%

Date/Time, File Pass to?



: Prel. Report

1) 02/12/2024



: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

1

Survey Fee:

Transportation

S + RS. SI

Fuel

Others

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format:

MER-TP

Lump Sum / I.B.I. (\$

4100

TOTAL

CHOON HOCK MOTOR TRADING CO

25 November 2024

*Not Authorized
11 Lny @ 410dp
Resurvey After Paint
4 days*

ESTIMATE REPAIR BILL ON SH2264A TOYOTA COROLLA AXIO 1.5X

1 pce rear boot	R1	\$ 850.20	✓
1 pce rear boot inner garnish	brs	\$ 229.20	✓
2 pcs rear boot hinges	R	\$ 273.60	X
1 pce rear lock	nd	\$ 94.30	✓
1 pce rear boot outer holder	way	\$ 300.80	✓
1 pce rear boot logo	me	\$ 50.30	✓
2 pcs rear lamp	CM	\$ 1,198.40	✓
2 pcs rear lamp inner panel	ol/R1	\$ 267.60	2x
1 pce rear bumper	R1	\$ 530.50	✓
2 pcs rear bumper side retainer	DIT	\$ 184.60	✓
1 pce rear panel	R1	\$ 602.20	2✓
1 pce rear panel garnish	nd	\$ 218.90	✓
1 pce rear boot rubber	DIS/nd	\$ 185.20	50/nd 91.60sw
1 pce rear exhaust pipe	R	\$ 372.30	X
2 pcs rear exhaust pipe rubber	Sn	\$ 62.60	X
		\$ 5,420.70	
	less 20%	\$ 1,084.15	
		\$ 4,336.55	

S/NETT

1 pce rear sensor	nd	\$ 220.00	200sw
Towing	(Bill)	\$ 180.00	70cl
Remove and refit sensor		\$ 100.00	5cl
Remove and refit exhaust pipe	nn	\$ 180.00	X
Wiring		\$ 100.00	2cl
Panel beating		\$ 1,300.00	60cl
Spray painting		\$ 1,500.00	80cl
Rustproof		\$ 150.00	6cl
Total amount :		\$ 8,066.55	NETT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Mailing address: 28 Surrey Road #18-03 Singapore 1107762 Reg No: 30568200L
Tel: (65) 64530778 Email: choonhockmotor@gmail.com

Acknowledged by Repairer

Signature:

Date: