

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0890/2024/EQ
DATE : 27-Nov-24
WIP : 39713

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 29/11/2024

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Motor Claims Dept

Hi Steve,

6 Days + 1 Sun + 1 PH - OK - Allan Boo

25-Feb-25

OWNER'S NAME : MR LEONG YEW MENG
ADDRESS : 13 POH HUAT TERRACE
SINGAPORE 545138

TELEPHONE : HP +65 98691818
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7230024167-01
VEHICLE NO : **SLZ 69 Z**
MODEL CODE : AUDI E-TRON GT
MODEL YEAR : 11/4/2022
ENGINE NO : EBG 063349
CHASSIS NO : WAUZZZFW2N7006777
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 24-Nov-24
PLACE OF ACCIDENT : 703 HOUGANG AVE 2, BLOCK 703, SINGAPORE 530703

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLZ 69 Z

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$ 480.00
2	TO CARRY OUT CALIBRATION FOR 360 DEGREE CAMERA SYSTEM WITH VAS TOOLS.	S/N \$	800.00	\$ 800.00
3	TO DISMANTLE AND RENEW FRONT BUMPER AND LHS FENDER. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,800.00	\$ 1,200.00
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	\$	2,000.00	\$ 1,300.00
5	TO DE-ENERGEISING HIGH VOLTAGE SYSTEM, DEACTIVATION AND ACTIVATION.	S/N \$	480.00	\$ 480.00
6	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	292.00	\$ 292.00
TOTAL LABOUR CHARGES		:	\$ 5,852.00	\$ 4,552.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLZ 69 Z

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 3,843.00	
2	FRONT BUMPER AIR GUIDE - LH	1	\$ 223.00	
3	FRONT BUMPER GUIDE SECTION - LH	1	\$ 41.00	
4	FRONT FENDER - LH	1	\$ 6,248.00	\$ 4,998.40
5	FRONT FENDER SUPPORT - LH	1	\$ 220.00	
6	FRONT CONSOLE - LH	1	\$ 460.00	
7	FRONT FENDER SUPPORT - LH	1	\$ 99.00	
8	FRONT FENDER BRACKET - LH	1	\$ 40.00	
9	FRONT FENDER BRACKET - LH	1	\$ 40.00	
10	FRONT FENDER BRACKET - LH REAR	1	\$ 46.00	
11	FRONT WHEEL HOUSING LINER - UPPER	1	\$ 381.00	
12	FRONT WHEEL HOUSING LINER - LOWER	1	\$ 209.00	
13	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 12,250.00	\$ 4,998.40
TOTAL LABOUR CHARGES		:	\$ 5,852.00	\$ 4,552.00
GRAND TOTAL		:	\$ 18,102.00	\$ 9,550.40

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT