



HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921

Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhb.com.sg

Company Reg. No. 202341776E

辉皇鸿寶

Vehicle No.: SNQ5520C
Make/Model : Toyota Sienta
Chassis no.: JTD8BBA350L001649
Year of Manufacture : 2024

Date of survey: 26/11/2024
Surveyor: Adrian
Company : LKK
Ins Company : Income
TP vehicle No.: SME2367Z

TP INC
Veron

Accident Date : 22 Nov 2024

Type of repair: Part by Parts

Estimate cost of repairs

Qty	Part Description	Unit Price	Total Price
1 pc	Rear bumper <i>Delnd</i>	\$ 488.00	\$ 488.00 ✓
1 pc	Rear tailgate <i>Dented</i>	\$ 1 890.00	\$ 1 890.00 ✓
1 pc	Rear tailgate glass moulding <i>new</i>	\$ 54.00	\$ 54.00 ✓
1 pc	Rear tailgate logo <i>new</i>	\$ 90.00	\$ 90.00 ✓
1 pc	Rear tailgate "Hybrid" emblem <i>new</i>	\$ 68.00	\$ 68.00 ✓
2 pcs	Rear tailgate hinge RH/LH <i>new</i>	\$ 88.00	\$ 176.00 ✓
1 pc	Rear tailgate lock <i>Jammed</i>	\$ 629.00	\$ 629.00 ✓ 498
1 pc	Rear end panel <i>Dented</i>	\$ 616.00	\$ 616.00 ✓
1 pc	Rear end panel top garnish <i>new</i>	\$ 199.00	\$ 199.00 ✓
2 pc	Rear reverse sensor <i>new</i>	\$ 503.00	\$ 1,006.00 560
4 pc	Rear reverse sensor cover <i>2 pieces new</i>	\$ 65.00	\$ 260.00 200/100
Less 20% <i>75%</i>		4274	\$ 5,476.00
		3205.50	\$ (1,095.20)
			\$ 4,380.80

1 set	Rear bumper clips <i>new</i>	\$ 50.00 SN 30
1 set	Tailgate trim board clips <i>new</i>	\$ 50.00 SN 1
1 set	Tailgate windscreen sealant <i>new</i>	\$ 60.00 SN ✓
1 set	Tailgate windscreen cleaner <i>new</i>	\$ 40.00 SN 30
1 set	Tailgate windscreen sponge <i>new</i>	\$ 40.00 SN 30
1 set	Rear end panel garnish clips <i>new</i>	\$ 50.00 SN 210
1 set	Rear end panel sealant <i>new</i>	\$ 60.00 SN 2
		\$ 350.00

\$4,505.00
(3,106.75)
\$ 3,378.75

\$ 260.00



辉皇鸿寶

HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921

Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhbm.com.sg

Company Reg. No. 202341776E

1 job	To putty and spray painting	\$ 600.00 400
1 job	To remove, refix reverse sensor	\$ 100.00 50
1 job	To remove, refix reverse camera	\$ 100.00 50
1 job	To remove, refix rear windscreen glass	\$ 120.00 ✓
1 job	To remove, transfer and refix tailgate fittings	\$ 100.00 60
1 job	Tuff coat	\$ 60.00 ✓
1 job	Labour to remove rear accident damaged parts in order to repairs including panel beat and replace above parts.	\$ 800.00 600

1340

\$ 1,880.00

\$1,340.00

Grand-total

\$ 6,610.80

\$ 4,978.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

0

Admin L

1/s 26/11/24

No of Days: 26

Supplementary: All

total: 5166.50
CP/P)



HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhbm.com.sg
Company Reg. No. 202341776E

辉皇鸿寶

Vehicle No.: SNQ5520C
Make/Model: Toyota Sienta
Chassis no.: JTD8BBA350L001649
Year of Manufacture: 2024

Date of survey: 26/11/2024
Surveyor: Adrian
Company: LKK
Ins Company: Income
TP vehicle No.: SN E2367Z

Accident Date: 22 Nov 2024

Type of repair: Part by Parts

Supplementary

Qty	Part Description	Unit Price	Total Price
1 pc	Rear tailgate weatherstrip <i>cut</i>	\$ 451.00	\$ 451.00 ✓
1 pc	Electrical key antenna <i>cut</i>	\$ 97.00	\$ 97.00 ✓

Less 25%

548

\$ 548.00
\$ (137.00)
\$ 411.00

\$411.00

Supplementary: *All*

Adrian
27/11/24

Part: \$ 3,378.75
Supp: \$ 411.00
SLW \$ 260.00
Labour \$ 1,340.00
\$ 5,389.75

P/P \$ 5,389.75 @ 6 days