



HHHB PTE LTD

2 Kaki Bukit Ave 2 | #02-11 Kaki Bukit @ Autohub | Singapore 417921
Office: 6844 7414 | Fax: 6844 7401 | Email: claims@hhbm.com.sg
Company Reg. No. 202341776E

辉皇鸿寶

Vehicle No.: SNQ5520C
Make/Model: Toyota Sienta
Chassis no.: JTDBBBA350L001649
Year of Manufacture: 2024

Date of survey: 26/11/2024
Surveyor: Adrian
Company: LKK
Ins Company: Income
TP vehicle No.: SN E2367Z

Accident Date: 22 Nov 2024

Type of repair: Part by Parts

Supplementary

Qty	Part Description	Unit Price	Total Price
1 pc	Rear tailgate weatherstrip <i>cut</i>	\$ 451.00	\$ 451.00 ✓
1 pc	Electrical key antenna <i>cut</i>	\$ 97.00	\$ 97.00 ✓

Less 25%

548

\$ 548.00
\$ (137.00)
\$ 411.00

\$411.00

Supplementary: *All*

Adrian
27/11/24

Part: \$ 3,378.75
Supp: \$ 411.00
SLW \$ 260.00
Labour \$ 1,340.00
\$ 5,389.75

P/P \$ 5,389.75 @ 6 days