

ADJUSTMENT ON REPAIR COST & REPLACEMENT OF PARTS

Vehicle No. : SLF9739U
 Chassis No. : RU11204710
 Engine No. : L15B4404710
 Date of Accident : 21.11.2024

Reference No. : 241121-TPC-JSSM05
 Make/Model : HONDA / VEZEL
 Date : 26.11.2024

Replacement of Damaged Parts

S/No.	QTY	Description	Condition / Remarks	Repairer's Estimates
1	1	Front RH Headlamp	Damaged CM	\$ 1,899.00
2	1	Front RH Headlamp Retainer	Necessary ^ ^	\$ 215.00
3	1	Front RH Fender	Buckled 00	\$ 898.00
4	1	Front RH Fender Garnish	Damaged 00/100	\$ 355.00
5	1	Front Bumper Bracket no to cm	Necessary cm	\$ 142.00
6	1	Front RH Door Hinges	Distorted ^ ^	\$ 110.00
7	1	Front Bonnet	Buckled 00/200	\$ 1,677.00
8	10	Front RH Fender Garnish Clips	Necessary ^ ^	\$ 80.00
				\$ 5,376.00

Total (Parts): \$ 5,376.00
 -20% \$ 4,300.80

Labour Charges

9	To fix & dismantle and remove damaged Front Right Portions; affected damaged portion.	\$ 1,000.00
10	To apply anti rust coat and affected areas	\$ -
11	To check wiring	\$ 180.00
12	Welding and cutting of affected panels, including chassis alignment.	\$ -
13	Spray painting for Rear Portions affected parts	\$ 900.00
14	Programming for Hybrid System Reset	\$ -
15	Diagnose ECU system and reset error code.	\$ -
16	3D Wheel Alignment	\$ -
17	To Apply Waterproofing sealer on End and Front Support Panels	\$ -

Total Labour: \$ 2,080.00

Total cost of repairs (Total cost of parts + Total Labour Cost) \$ 6,380.80

Less 20% **\$ 5,104.64**

JSSM AUTOSOLUTIONS PTE LTD

Page 1

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) for the resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Not Authorized
 the
 means
 90096608
 L/S #3100/
 26/11/24
 Take photo after repair

P-3869.50
 202
 3095.60
 810
 3945.6
 202
 3150