



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

Tax Invoice

STRIDES PREMIER AUTOMOTIVE SERVICES PL.
60 WOODLANDS INDUSTRIAL PARK E4
SINGAPORE 757705

INV No. : SAC2401626

INV Date : 02-12-2024

Reference CS3/SMR24110528/Enp3m4

Code SMR

PROFESSIONAL SERVICE FEE

Vehicle No. SMW 7522P
Insured Veh. SHB 5905B
Claim No. TAX/11/24/2075
Policy No.
Accident Date 21/11/2024
Inspection Date 27/11/2024

Description	Amount
Pre-Repair Survey	128.00
Sub-Total	128.00
GST (9%)	11.52
Grand Total	139.52

We shall be glad if you could forward the payment at your earliest convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

SML



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS STRIDES PREMIER AUTOMOTIVE SERVICES PL.	Ref:	CS3/SMR24110528/Enp3m4
60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705	Date:	02/12/2024
	Code:	SMR

1. Policy Particulars :- PRE-REPAIR SURVEY

Insured Veh.	SHB 5905B	Veh. Inspected	SMW 7522P
Policy No.	-	Coverage	0
Claim No.	TAX/11/24/2075	Excess	\$0.00
Assign From	HUA YEN	Assign Date	26/11/2024

2. Vehicle Details

Make & Model	TOYOTA COROLLA HYBRID	C.C	1798
Engine No.	2ZR2H15719	Year of Reg.	08/12/2020
Chassis No.	JTDBB3BE60J027887	Colour	BLACK
Odometer	441439 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: SPORTS RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	195/65R15	YOKOHAMA	5
L/H Front Tyre	195/65R15	YOKOHAMA	5
R/H Rear Tyre	195/65R15	YOKOHAMA	5
L/H Rear Tyre	195/65R15	YOKOHAMA	5

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.

5. General Information

Accident Date	21/11/2024	Inspection Date	27/11/2024 (10:10)
Survey held at	LAY AUTO GARAGE PTE LTD - 48 TOH GUAN ROAD #02-103/104 ENTERPRISE HUB SINGAPORE 608586		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$4,000-\$5,000

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days

CTY

CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P





PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P




PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P




PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P




PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P




PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P



PHOTOGRAPHS FOR VEHICLE NO. : SMW 7522P

