

DATE : 10.07.2024

TO : INCOME
VEHICLE NO : SMU6168X
MODEL : HONDA CIVIC FC
DATE OF ACCIDENT : 25.06.2024
CHASSIS : MRHFC5650LT000010
DATE OF REG : 21.08.2020

Veron.

CLAIM DETAIL : PARTS

S/N	DESCRIPTION	QTY	UNIT LIST PRICE	TOTAL LIST PRICE
1	FRONT BUMPER <i>dehd</i>	1	\$ 658.60	\$ 658.60
2	FRONT BUMPER LOWER GRILLE <i>new</i>	1	\$ 154.60	\$ 154.60
3	FRONT BUMPER FOGLAMP <i>new</i>	1	\$ 398.60	\$ 398.60
4	FRONT BUMPER FOGLAMP COVER <i>stuck</i>	1	\$ 85.90	\$ 85.90
5	FRONT BUMPER REINFORCEMENT <i>perforated</i>	1	\$ 439.20	\$ 439.20
6	FRONT BUMPER RETAINER <i>new</i>	1	\$ 68.30	\$ 68.30
7	FRONT BONNET TOP RUBBER <i>not ~</i>	1	\$ 135.60	\$ 135.60
8	FRONT GRILLE <i>crackd</i>	1	\$ 318.60	\$ 318.60
9	FRONT GRILLE LOGO <i>new</i>	1	\$ 68.40	\$ 68.40
10	FRONT GRILLE CHROME <i>crackd</i>	1	\$ 198.40	\$ 198.40
11	FRONT SUPPORT PANEL <i>new</i>	1	\$ 510.20	\$ 510.20
12	FRONT SUPPORT PANEL TOP GARNISH <i>perforated</i>	1	\$ 37.70	\$ 37.70
13	FRONT WASHER TANK <i>new</i>	1	\$ 165.20	\$ 165.20
14	FRONT WASHER TANK MOTOR <i>new</i>	1	\$ 125.80	\$ 125.80
15	FRONT BUMPER SIGNAL LAMP <i>new</i>	1	\$ 78.50	\$ 78.50
16	FRONT FENDER RH <i>new</i>	1	\$ 468.60	\$ 468.60
17	FRONT FENDER SIGNAL LAMP RH <i>new</i>	1	\$ 72.50	\$ 72.50
18	FRONT FENDER TOP SPONGE RH <i>new</i>	1	\$ 45.30	\$ 45.30
19	FRONT FENDER COWLING <i>new</i>	1	\$ 142.50	\$ 142.50
20	HEADLAMP (HID) RH <i>crackd</i>	1	\$ 1,435.60	\$ 1,435.60
21	HEADLAMP TOP CHROME <i>new</i>	1	\$ 149.60	\$ 149.60
22	HEADLAMP LOWER BRACKET <i>new</i>	1	\$ 58.20	\$ 58.20
23	HEADLAMP TOP GARNISH <i>new</i>	1	\$ 144.20	\$ 144.20
24	HEADLAMP TOP RUBBER <i>new</i>	1	\$ 45.30	\$ 45.30
25	RADIATOR SIDE GARNISH RH <i>new</i>	1	\$ 85.60	\$ 85.60

26. FRONT NUMBER PLATE GARNISH - \$102.40
27. TOP GARNISH - \$204.50

TOTAL PRICE \$ 6,091.00
LESS 20% \$ 1,218.20
SUB TOTAL PRICE \$ 4,872.80

3178.40

2542.72

365

1279

S/N	DESCRIPTION	QTY	UNIT S/NETT	TOTAL S/NETT
1	FRONT BUMPER CLIP (SET) <i>new</i>	1	\$ 50.00	\$ 50.00
2	FRONT BUMPER LOWER LIP (ACCESSORIES) <i>new</i>	1	\$ 850.00	\$ 850.00
3	FRONT FENDER INNER COWLING CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
4	HEADLAMP TOP GARNISH CLIP (SET) <i>new</i>	1	\$ 30.00	\$ 30.00
TOTAL				\$ 960.00

30
500
+
+
530

CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)

S/N	JOB DESCRIPTION	PRICE	ADJUSTED COST
1	PANEL BEATING, REMOVING AND REPLACING PARTS	\$ 1,200.00	300
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,200.00	200
3	COMPUTERISED WHEEL ALIGNMENT	\$ 120.00	+
4	REFOCUS HEADLAMP BEAM	\$ 80.00	+
5	TO CHECK DIAGNOSTICS OF VEHICLE MANAGEMENT/CONTROL UNITS, RESET MEMORIES TO SPECIFICATION ETC.	\$ 150.00	+
TOTAL		\$ 2,750.00	

500

ESTIMATE REPORT

TOTAL PARTS COST : \$ 5,832.80
TOTAL LABOUR COST : \$ 2,750.00
TOTAL REPAIR COST : \$ 8,582.80

Adrian G.
L/S 11/07/24.
03 ep.

Supplementary: 72
total: 364472
L/S: 291k

2.91k

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REQUEST FOR SUPPLEMENTS PARTS

Vehicle No	SMU6168X	Date of Request	11.07.2024
Vehicle Model	HONDA CIVIC	Number of Days to Extend (If any)	

S/N	PART DESCRIPTION		LIST PRICE
1	HORN ASSEMBLY (S/NETT) <i>Payd</i>	1SET	\$180.00

90.

90
Supplementary: 72