

N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

TP INC
Veron.

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

Contact : 87420435 80606347

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BONNET <i>Dented</i>	1	1105.40	✓ 1,105.40
FRONT BONNET HINGES L/R <i>Best</i>	2	81.80	✓ 163.60
FRONT BONNET INSULATOR <i>new</i>	1	388.20	+ 388.20
FRONT BONNET MECHANISM LOCK <i>new</i>	1	188.80	+ 188.80
FRONT BONNET OUTER GARNISH <i>new</i>	1	406.50	+ 406.50
FRONT BUMPER FOGLAMP GARNISH LH <i>cut</i>	1	134.60	✓ 134.60
FRONT BUMPER L/R <i>LH Disturbed, RH torn</i>	2	1418.20	1952 ✓ 2,836.40
FRONT BUMPER LOWER REINFORCEMENT <i>new</i>	1	440.90	+ 440.90
FRONT BUMPER LOWER REINFORCEMENT SPONGE <i>cut</i>	1	111.00	- 111.00
FRONT BUMPER PARKING SENSOR HOLDER <i>new</i>	2	55.20	✓ 110.40
FRONT BUMPER PARKING SENSOR LH <i>new</i>	1	503.90	✓ 503.90 <i>320</i>
FRONT BUMPER PARKING SENSOR O-RING LH <i>new</i>	1	20.00	✓ 20.00
FRONT BUMPER REINFORCEMENT <i>new</i>	1	803.60	✓ 803.60
FRONT BUMPER SIDE GARNISH LH <i>cut</i>	1	86.90	✓ 86.90
FRONT BUMPER SIDE RETAINER L/R <i>LH new</i>	2	140.30	14030 ✓ 280.60
FRONT BUMPER SPONGE <i>cut</i>	1	111.00	✓ 111.00
FRONT BUMPER UNDER COVER <i>torn</i>	1	653.20	✓ 653.20
FRONT GRILLE ASSY <i>cut</i>	1	3460.20	✓ 3,460.20 <i>1890</i>

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

FRONT KNUCKLE ARM BEARING L/R <i>RH Dmd</i>	2	846.90	1,693.80 <i>846.90</i>
FRONT KNUCKLE ARM L/R <i>RH Dmd</i>	2	974.10	1,948.20 <i>974.10</i>
FRONT LH FENDER <i>Dislud</i>	1	1312.10	1,312.10 <i>990.</i>
FRONT LH FENDER ARCH GARNISH <i>new</i>	1	186.40	186.40
FRONT LH FENDER GLASS WITH MOULDING <i>new</i>	1	528.70	528.70 <i>180.</i>
FRONT LH FENDER INNER ARCH PANEL <i>Regis</i>	1	891.70	891.70
FRONT LH FENDER INNER BRACKET <i>But</i>	1	151.30	151.30
FRONT LH FENDER INNER SHIELD <i>Rehnd</i>	1	401.90	401.90 <i>219.</i>
FRONT LH HEADLAMP <i>Canld</i>	1	4421.00	4,421.00 <i>4040</i>
FRONT LH HEADLAMP INNER TOP PANEL <i>Buehnd</i>	1	476.60	476.60 <i>265</i>
FRONT LH WIRE HARNESS <i>new</i>	1	8760.20	8,760.20
FRONT LH WIRE HARNESS COVER <i>Canld</i>	1	215.00	215.00
FRONT LOWER ARM L/R <i>RH But</i>	2	1175.80	2,351.60 <i>1175.80</i>
FRONT RH FENDER INNER SHIELD <i>new</i>	1	401.90	401.90
FRONT RIM CAP L/R <i>RH ut.</i>	2	294.40	588.80 <i>294.40</i>
FRONT SHOCK ABSORBER L/R <i>new</i>	2	660.00	1,320.00
FRONT SHOCK ABSORBER TOP MOUNTING L/R <i>new</i>	2	328.00	656.00
FRONT STABILIZER LINK L/R <i>new</i>	2	328.00	656.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

FRONT WIPER GARNISH	<i>Crack d</i>	1	924.40	✓	924.40
FRONT WIPER GARNISH COVER LH	<i>Del d</i>	1	39.00	✓	39.00
REAR BUMPER	<i>Distorted</i>	1	2191.00	✓	2,191.00 1460
REAR BUMPER END SEAL COVER LH	<i>tom</i>	1	223.20	✓	223.20
REAR BUMPER REFLECTOR LH	<i>smashed</i>	1	53.10	✓	53.10
REAR BUMPER REVERSE SENSOR	<i>1 piece dnd</i>	2	630.40	✓	1,260.80 360
REAR BUMPER REVERSE SENSOR HOLDER	<i>4 pieces dnd</i>	4	41.80	✓	167.20 167.20
REAR BUMPER REVERSE SENSOR O-RING	<i>1 piece new</i>	2	31.10	✓	62.20 31.10
REAR BUMPER REVERSE SENSOR WIRE HARNESS	<i>new</i>	1	151.30	✓	151.30
REAR BUMPER SIDE RETAINER L/R	<i>1H dnd</i>	2	121.30	✓	242.60 121.30
REAR END PANEL	<i>Del d</i>	1	1134.50	✓	1,134.50
REAR END PANEL INNER TOP GARNISH	<i>Del d new</i>	1	210.90	✓	210.90
REAR LH FENDER	<i>Distorted</i>	1	1692.60	✓	1,692.60
REAR LH FENDER GLASS WITH MOULDING	<i>new dnd</i>	1	1138.30	✓	1,138.30 140
REAR LH FENDER INNER AIR VENT	<i>Del d</i>	1	188.80	✓	188.80
REAR LH FENDER INNER PANEL	<i>Del d</i>	1	596.20	✓	596.20
REAR LH FENDER INNER SHIELD	<i>tom</i>	1	309.60	✓	309.60
REAR LH FENDER INNER TRIM BOARD	<i>Del d</i>	1	745.70	✓	745.70

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

REAR LH FENDER OUTER GARNISH (CABLE COVER) <i>Delid</i>	1	186.40	<i>✓</i>	186.40
REAR LH FENDER PETROL LID <i>Revis</i>	1	216.50	<i>+</i>	216.50
REAR LH FENDER PETROL LID LOCK CABLE <i>new</i>	1	60.50	<i>+</i>	60.50
REAR LH FENDER PETROL LID RIVET <i>new</i>	1	18.70	<i>+</i>	18.70
REAR LH SLIDING DOOR RAIL <i>new</i>	1	456.30	<i>+</i>	456.30
REAR LH SLIDING DOOR RAIL COVER <i>new</i>	1	702.90	<i>✓</i>	702.90
REAR LH TAILLAMP <i>new</i>	1	1092.90	<i>✓</i>	1,092.90 <i>818</i>
REAR LH TAILLAMP INNER PANEL <i>Distorted</i>	1	343.00	<i>✓</i>	343.00
REAR LH TAILLAMP LOWER GARNISH <i>Distorted</i>	1	223.20	<i>✓</i>	223.20
REAR LH TAILLAMP LOWER GARNISH SIDE BRACKET <i>new</i>	1	157.10	<i>✓</i>	157.10
REAR TAILGATE <i>Distorted</i>	1	2773.70	<i>✓</i>	2,773.70 <i>2340</i>
REAR TAILGATE 'HYBRID' EMBLEM <i>new</i>	1	66.30	<i>✓</i>	66.30
REAR TAILGATE 'LOGO' EMBLEM <i>new</i>	1	93.30	<i>+</i>	93.30
REAR TAILGATE 'NOAH' EMBLEM <i>new</i>	1	66.30	<i>+</i>	66.30
REAR TAILGATE DAMPER L/R <i>new</i>	2	487.10	<i>+</i>	974.20
REAR TAILGATE HINGES L/R <i>new</i>	2	94.10	<i>+</i>	188.20
REAR TAILGATE INNER RUBBER SIDE STOPPER LH <i>new</i>	1	31.10	<i>+</i>	31.10
REAR TAILGATE INNER RUBBER STOPPER LH <i>new</i>	1	27.60	<i>+</i>	27.60

*** This is a computer-generated document which requires no signature.***

page 4

Engine under cover — 296.00 ✓ torn
— side cover kit — 196.00 ✓ found

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

REAR TAILGATE INNER TRIM BOARD <i>Build</i>	1	886.30	<i>E</i>	886.30
REAR TAILGATE MECHANISM LOCK <i>new</i>	1	647.10	<i>+</i>	647.10
REAR TAILGATE OUTER GARNISH <i>new</i>	1	701.40	<i>+</i>	701.40
REAR TAILGATE REFLECTOR LH <i># Build</i>	1	355.40	<i>E</i>	355.40
REAR TAILGATE WINDSCREEN <i>new</i>	1	1932.50	<i>+</i>	1,932.50
REAR TAILGATE WINDSCREEN MOULDING <i>new</i>	1	298.00	<i>✓</i>	298.00
Subtotal before discount				62,596.70
Percentage discount 25%				15,649.18
Sub-total 1				46,947.53
FRONT BONNET INSULATOR CLIPS - SET <i>new</i>	1	50.00	<i>+</i>	50.00
FRONT BONNET OUTER GARNISH CLIPS - SET <i>new</i>	1	30.00	<i>+</i>	30.00
FRONT BUMPER CLIPS - SET <i>new</i>	1	50.00	<i>✓</i>	50.00
FRONT LH FENDER ARCH GARNISH CLIPS - SET <i>new</i>	1	25.00	<i>+</i>	25.00
FRONT LH FENDER GLASS SEALANT <i>new</i>	1	80.00	<i>30</i>	80.00
FRONT LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
FRONT RH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	<i>+</i>	50.00
FRONT TYRES L/R 205/60R16 <i>new</i>	2	480.00	<i>+</i>	960.00
FRONT WHEEL RIM L/R <i>RH new new</i>	2	500.00	<i>+</i>	1,000.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@nts1.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466

Date in : 25/11/2024

Vehicle Num. : SNM3240U

Model : TOYOTA NOAH HYBRID 1.8X CVT

Chassis/Eng# : ZWR900097321/2ZR2V43037

FRONT WIPER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
REAR BUMPER CLIPS - SET <i>new</i>	1	80.00	<i>30</i>	80.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>new</i>	1	50.00	<i>20</i>	50.00
REAR LH FENDER GLASS SEALANT <i>new</i>	1	80.00	<i>40</i>	80.00
REAR LH FENDER INNER SHIELD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR LH FENDER INNER TRIM BOARD CLIPS - SET <i>new</i>	1	50.00	<i>30</i>	50.00
REAR LH FENDER OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>20</i>	40.00
REAR LH TAILLAMP CLIPS - SET <i>new</i>	1	25.00	<i>X</i>	25.00
REAR LH TAILLAMP LOWER GARNISH CLIPS - SET <i>new</i>	1	25.00	<i>20</i>	25.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>new</i>	1 <i>410</i>	50.00	<i>30</i>	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>new</i>	1	40.00	<i>X</i>	40.00
REAR TAILGATE WINDSCREEN SEALANT <i>new</i>	1	80.00	<i>60</i>	80.00
Subtotal before discount				2,905.00
Percentage discount 0%				0.00
Sub-total 2				2,905.00
Parts-total				49,852.53

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To reset system after repair works

30 ~~80.00~~
X ~~500.00~~

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200616038C
GST Registration No. : 200616038C

CAPITAL CAR LEASING PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI
INDUSTRIAL PARK
SINGAPORE 408934

Contact : 87420435 80606347

TAX INVOICE

Repair Code : CLM18466
Date in : 25/11/2024
Vehicle Num. : SNM3240U
Model : TOYOTA NOAH HYBRID 1.8X CVT
Chassis/Eng# : ZWR900097321/2ZR2V43037

To remove, reinstall electrical wiring harness, check lighting, and rewire for parking sensor.	✓	80.00
To remove, reinstall tailgate windscreen	120	150.00
To remove, reinstall fender glass	50	240.00
To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.	200	480.00
To road test driving, check and resetting wheel alignments system.	80	100.00
To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)	80	100.00
To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.	2000	3,200.00
To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.	2000	3,300.00
To apply anti-rust chemical on repaired and replaced panel.	100	300.00
To remove, reinstall tailgate mechanism and check for function	80	80.00
Labour Total		8,610.00
Parts & Labour Total		58,462.53

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

*** This is a computer-generated document which requires no signature. ***
page 7

Adrian L
2/5 26/11/24
18 Apr

total 28496.27
1/5 22.81K

22.81K