

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LEE BOON SOON
BLK 363 HOUGANG AVE 5 #02-282
SINGAPORE 530363

Contact : 96337846

TPINC
HuiRong
TAX INVOICE

Repair Code : CLM16486

Date in : 25/11/2024

Vehicle Num. : SLF2824C

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W70J004888/2ZR1820226

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER <i>Del'd</i>	1	911.60	911.60 785
FRONT BUMPER SIDE RETAINER RH <i>Del'd</i>	1	71.20	71.20 2
FRONT RH DOOR <i>Repair</i>	1	996.30	+ 996.30
FRONT RH DOOR BLACK TAPE	1	161.20	+ 161.20
FRONT RH DOOR CHECKER	1	199.80	+ 199.80
FRONT RH DOOR HINGE (LOWER)	1	76.30	+ 76.30
FRONT RH DOOR HINGE (TOP) <i>New</i>	1	76.30	+ 76.30
FRONT RH DOOR SIDE MIRROR ASSY	1	481.70	+ 481.70
FRONT RH DOOR SIDE MIRROR COVER <i>new could</i>	1	172.50	172.50 795
FRONT RH FENDER <i>Painted</i>	1	1502.50	1502.50 795
FRONT RH FENDER INNER SHIELD COVER <i>Del'd</i>	1	188.50	✓ 188.50
FRONT RH FENDER QUARTER GLASS WITH MOULDING <i>new</i>	1	197.90	+ 197.90
FRONT RH HEADLAMP <i>lt</i>	1	1951.00	✓ 1,951.00
FRONT RH KNUCKLE ARM <i>end</i>	1	878.60	878.60 725.2
FRONT RH LOWER ARM <i>Bent</i>	1	681.50	681.50 598
FRONT RH SHOCK ABSORBER <i>new</i>	1	855.40	+ 855.40
FRONT RH SPORT RIM <i>lt</i>	1	1979.20	1979.20 550/sw
FRONT RH TIE ROD END <i>new</i>	1	155.30	+ 155.30

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LEE BOON SOON
BLK 363 HOUGANG AVE 5 #02-282
SINGAPORE 530363

Contact : 96337846

TAX INVOICE

Repair Code : CLM16486

Date in : 25/11/2024

Vehicle Num. : SLF2824C

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W70J004888/2ZR1820226

FRONT RH WHEEL BEARING	1	181.70	✓	181.70
Subtotal before discount		5459.50		11,718.50
Percentage discount 25%		4094.92		2,929.63
Sub-total 1		8-N-550		8,788.88
FRONT BUMPER CLIPS - SET	1	50.00	30	50.00
FRONT RH DOOR INNER TRIM BOARD CLIPS - SET	1	50.00	+	50.00
FRONT RH FENDER INNER SHIELD COVER CLIPS - SET	1	30.00	✓	30.00
FRONT RH FENDER QUARTER GLASS WITH MOULDING SEALANT	1	80.00	40	80.00
FRONT RH TYRE	1	380.00	+	380.00
Subtotal before discount				590.00
Percentage discount 0%				0.00
Sub-total 2				590.00
Parts-total				9,378.88

LABOUR

To remove, reinstall electrical wiring harness, check lighting and resetting headlamp focussing. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To transfer door glass, regulator gear, motor, railing, channel, trim board, mechanism lock and handle.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

30 80.00

✓ 140.00

80 100.00

+

600 1,000.00

*** This is a computer-generated document which requires no signature.***

TwinCar AUTOMOTIVE PTE LTD

Company Registration and GST No. 200714616M

2 Kaki Bukit Avenue 2 #01-17 Kaki Bukit Autohub, Singapore 417921

Tel: 67440510

Fax: 67410510

Email: sales@n51.com.sg

LEE BOON SOON

BLK 363 HOUGANG AVE 5

#02-282

SINGAPORE 530363

Repair Code: CLM16486

Date in: 25/11/2024

Vehicle No.: SLF2824C

Model: TOYOTA WISH 1.8 CVT

Chassis/Eng#: JTDGG20W70J004888/2ZR1820226

SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	FRONT BUMPER REINFORCEMENT <i>Dented</i>	L	1	\$ 470.40	\$ 470.40
2	FRONT BUMPER SPONGE <i>one</i>	L	1	\$ 141.20	\$ 141.20
3	FRONT WASHER TANK <i>Dented</i>	L	1	\$ 96.50	\$ 96.50
4	FRONT WASHER TANK NECK <i>new</i>	L	1	\$ 34.60	\$ 34.60
	Sub total before discount:				\$ 742.70
	Percentage discount 25%:				\$ 185.68
	Sub-total 1 :				\$ 557.03
	Parts Total:				\$ 557.03

Adrian Lij
27/11/24.

708.10
Supplementary: 531.07

Hussain & Sons Workshop

2 Kaki Bukit Avenue 2
#02-16 Kaki Bukit Autohub
Singapore 417921

Phone Number: 6744 9663

Fax Number: 6748 4765

Customer: TOYOTA WISH SLF2824C
Company: TWINCAR AUTOMOTIVE PTE
License NO: SLF2824C
Odometer:

Date: 25/11/2024 5:54 PM
VIN
Technician: BENSON
Order NO: MSA

VEHICLE ALIGNMENT REPORT

TOYOTA, WISH ZGE20G (2WD), 09-10 (Customized)

Primary Angles

Primary Angles			Initial	Specifications		Final
Front	Caster	Left	----	Min.	Max.	----
		Right	----	2.33°	3.82°	----
	Camber	Left	----	2.33°	3.82°	----
		Right	-0.85°	-1.25°	0.25°	-0.76°
	Toe	Left	-0.16°	-1.25°	0.25°	-2.10°
		Right	0.23°	-0.09°	0.09°	0.16°
		Total	0.04°	-0.09°	0.09°	0.01°
Rear	Camber	Left				
		Right				
	Toe	Left				
		Right				
		Total				
Max Thrust Angle						

Secondary Angles

		Initial	Specifications		Final
			Min.	Max.	
SAI	Left	----	11.33°	11.33°	----
	Right	----	11.33°	11.33°	----
Included Angle	Left	----	----	----	----
	Right	----	----	----	----
Toe Out On Turns	Left				
	Right				
Max Turn Inside	Left	----	----	----	----
	Right	----	----	----	----
Toe Curve Change	Left				
	Right				
Setback	Front				
	Rear				
Track Width Diff.					
Wheel Base Diff.					
Front Ride Height	Left				
	Right				
Rear Ride Height	Left				
	Right				
Frame Angle					

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

LEE BOON SOON
BLK 363 HOUGANG AVE 5 #02-282
SINGAPORE 530363

Contact : 96337846

TAX INVOICE

Repair Code : CLM16486

Date in : 25/11/2024

Vehicle Num. : SLF2824C

Model : TOYOTA WISH 1.8 CVT

Chassis/Eng# : JTDGG20W70J004888/2ZR1820226

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total	2,500.00
Parts & Labour Total	11,878.88

*** This is a computer-generated document which requires no signature.***

page 3

Admin Lj
L/s 26/11/24.

05 Rys
Supplementary: 531.07
Total: 6665.29
L/s: 5.3K

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5.3K