

# TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

KAREN GOH HWEE LI  
BLK 463 HOUGANG AVE 10 #02-962  
SINGAPORE 530463

Contact : 90089194

## TAX INVOICE

Repair Code : CLM16482

Date in : 25/11/2024

Vehicle Num. : SJW9283B

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106175332/3ZZ4995495

### Parts and Labour Assesment

| Description of part                              | Qty | Unit Price | Amount     |
|--------------------------------------------------|-----|------------|------------|
| REAR BOOT LID 'COROLLA' EMBLEM <i>new</i>        | 1   | 53.20      | ✓ 53.20    |
| REAR BOOTLID <i>Dented</i>                       | 1   | 949.10     | ✓ 949.10   |
| REAR BOOTLID 'ALTIS' EMBLEM <i>new</i>           | 1   | 53.20      | ✓ 53.20    |
| REAR BOOTLID 'LOGO' EMBLEM <i>new</i>            | 1   | 66.90      | ✓ 66.90    |
| REAR BOOTLID INNER RUBBER STOPPER L/R <i>new</i> | 2   | 18.00      | + 36.00    |
| REAR BOOTLID LOCK STRIKER <i>new</i>             | 1   | 20.90      | + 20.90    |
| REAR BOOTLID MECHANISM LOCK <i>Dented</i>        | 1   | 121.10     | ✓ 121.10   |
| REAR BOOTLID WEATHER STRIP <i>at</i>             | 1   | 209.90     | ✓ 209.90   |
| REAR BUMPER <i>Dented</i>                        | 1   | 660.80     | ✓ 660.80   |
| REAR BUMPER END SEAL COVER L/R <i>new</i>        | 2   | 105.00     | + 210.00   |
| REAR BUMPER REFLECTOR L/R <i>new</i>             | 2   | 46.90      | + 93.80    |
| REAR BUMPER SIDE BRACKET L/R <i>new</i>          | 2   | 37.60      | + 75.20    |
| REAR BUMPER SIDE RETAINER L/R <i>new</i>         | 2   | 78.70      | + 157.40   |
| REAR BUMPER SPONGE <i>new</i>                    | 1   | 153.80     | ✓ 153.80   |
| REAR END PANEL <i>Dented</i>                     | 1   | 727.70     | ✓ 727.70   |
| REAR END PANEL INNER TOP GARNISH <i>Dented</i>   | 1   | 231.60     | ✓ 231.60   |
| REAR END PANEL NOSE BRACKET L/R <i>Dented</i>    | 2   | 99.90      | ✓ 199.80   |
| REAR TAILLAMP L/R <i>PH and</i>                  | 2   | 514.70     | ✓ 1,029.40 |

514.70

\*\*\* This is a computer-generated document which requires no signature.\*\*\*



Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200714616M  
GST Registration No. : 200714616M

KAREN GOH HWEE LI  
BLK 463 HOUGANG AVE 10 #02-962  
SINGAPORE 530463

Contact : 90089194

## TAX INVOICE

Repair Code : CLM16482

Date in : 25/11/2024

Vehicle Num. : SJW9283B

Model : TOYOTA COROLLA ALTIS 1.6 AUTO

Chassis/Eng# : MR053ZEE106175332/3ZZ4995495

|                                              |            |   |        |    |          |
|----------------------------------------------|------------|---|--------|----|----------|
| REAR TAILLAMP LOWER BRACKET L/R              | new 394.50 | 2 | 71.90  | +  | 143.80   |
| Subtotal before discount                     |            |   |        |    | 5,193.60 |
| Percentage discount 25%                      |            |   |        |    | 1,298.40 |
| Sub-total 1                                  |            |   |        |    | 3,895.20 |
| REAR BUMPER CLIPS - SET                      | new        | 1 | 80.00  | 30 | 80.00    |
| REAR BUMPER REVERSE SENSOR - SET             | new        | 1 | 250.00 | 20 | 250.00   |
| REAR END PANEL INNER TOP GARNISH CLIPS - SET | new 250    | 1 | 40.00  | 20 | 40.00    |
| REAR TAILLAMP CLIPS L/R - SET                | new        | 2 | 25.00  | +  | 50.00    |
| Subtotal before discount                     |            |   |        |    | 420.00   |
| Percentage discount 0%                       |            |   |        |    | 0.00     |
| Sub-total 2                                  |            |   |        |    | 420.00   |
| Parts-total                                  |            |   |        |    | 4,315.20 |

## LABOUR

To transfer rear bootlid mechanism lock outer handle reflector

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total

Parts & Labour Total

2,560.00

6,875.20

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before repair painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

page 2

Total: 4766.12

4/s: 3.8k