

REF:

ASSIGNMENT

From: _____ Date: _____

Estimate No: _____

OD / TP RES / OD RES / EVA / INV / MV

To In: _____ Vehicle NO: _____

at W/O: _____

of _____

Insured: _____

Policy No: _____

Claims No: _____

Sum Insured: _____ Excess: _____

(Client Record)

Make of Vt: _____

(Policy Condition)

Remark: Trench had commenced its repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SMJ6503U Yr Regn: 2019, March.Type: M. Car / M. Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Volkswagen Golf C.D. 1395Colour: White A/C: Insured / Std / NI / NASp. Reading: 80539 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: WVWZZZAUZKW087312Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Nil / S/Rim / STD A/Rim orTyre Size: F: 225/45R17R: 225/45R17

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Continental

Front

Rear

R/Bal. 06 mm R/Bal. 06 mmL/Bal. 06 mm L/Bal. 06 mmD.O.A. _____ D.O.I. 27/11/24

Survey held at

Bifrost

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rees N/S, U/C, Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

TP / 1st Cap

COE Expiry: _____

Estimate given during: Yes ☒ No ☐
1st Survey: Yes ☒ No ☐MV: 69KPV: 25.3KNett: 43.7K

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Days Of Repair: _____

Resurvey No. of Trip: _____

Addl Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Inve (\$ _____)

Survey Fee: _____

Transportation: _____

3 + R8. \$1

Photos

Others

Report Format: _____

Report Form: _____

Bifrost Auto Pte Ltd

8 Kaki Bukit Ave 4 #01-49, Premier @ Kaki Bukit Singapore 415875
Tel: 93290237 Email: claims_rar@bifrostauto.com

SJE : _____
Date of Survey : _____
Date of ReSurvey: _____
Contacts : _____

Vehicle Nos : **SMJ 6503U**
Made : Volkswagen
Model : Golf 1.4 TSI CL
Chassis No : WVVZZZAUZKW087312

* AGREED Cost Of Repair and Repair Day/s with SJE *

Amount: _____

Working Day: _____

Nos.	PARTS	Qty	Unit S\$	TOTAL S\$
1	Front Bumper <i>Depend</i>	1	\$ 1,373.59	\$ ✓ 1,373.59
2	Front Bumper Spoiler Satin <i>Not in</i>	1	\$ 207.79	\$ + 207.79
3	Front Bumper Inner Bracket RH <i>3</i>	1	\$ 59.60	\$ + 59.60
4	Front Bumper Inner Bracket LH <i>3</i>	1	\$ 59.60	\$ + 59.60
5	Front Bumper Side Bracket RH <i>3</i>	1	\$ 25.25	\$ + 25.25
6	Front Bumper Side Bracket LH <i>3</i>	1	\$ 25.25	\$ + 25.25
7	Front Bumper Reinforcement <i>Not in</i>	1	\$ 726.84	\$ + 726.84
8	Front Bumper Sponge <i>Not in</i>	1	\$ 50.36	\$ + 50.36
9	Front Bumper Sensor Bracket <i>Not in</i>	4	\$ 16.04	\$ + 64.16
10	2K-Plastic Adhesive <i>Not in</i>	1	\$ 85.80	\$ + 85.80
11	Bonding Agent For Plastic <i>Not in</i>	1	\$ 68.71	\$ + 68.71
12	Front Bumper Centre Lower Grille <i>Not in</i>	1	\$ 165.60	\$ + 165.60
13	Front Bumper Fog Lamp Grille RH <i>3</i>	1	\$ 32.21	\$ + 32.21
14	Front Bumper Fog Lamp Grille LH <i>3</i>	1	\$ 32.21	\$ + 32.21
15	Front Bumper Fog Lamp Grille Lower Trim RH <i>3</i>	1	\$ 106.39	\$ + 106.39
16	Front Bumper Fog Lamp Grille Lower Trim LH <i>3</i>	1	\$ 106.36	\$ + 106.36
17	Front Bumper Fog Lamp RH <i>3</i>	1	\$ 301.56	\$ + 301.56
18	Front Bumper Fog Lamp LH <i>3</i>	1	\$ 301.56	\$ + 301.56
19	Front Bumper Centre Bracket <i>Not in</i>	1	\$ 63.67	\$ + 63.67
20	Temperature Sensor <i>Not in</i>	1	\$ 45.76	\$ + 45.76
21	Front Lock Carrier (Front Support Panel) <i>Not in</i>	1	\$ 1,219.56	\$ + 1,219.56
22	Front Headlamp Assembly RH <i>3</i>	1	\$ 2,123.04	\$ + 2,123.04
23	Front Headlamp Assembly LH <i>3</i>	1	\$ 2,123.04	\$ + 2,123.04
24	Front Headlamp Top Panel RH <i>3</i>	1	\$ 34.83	\$ + 34.83
25	Front Headlamp Top Panel LH <i>3</i>	1	\$ 34.83	\$ + 34.83
26	Radiator Grille <i>Not in</i>	1	\$ 513.52	\$ + 513.52
27	Front Bonnet <i>Not in</i>	1	\$ 1,206.36	\$ + 1,206.36
28	Front Bonnet Insulator <i>3</i>	1	\$ 210.76	\$ + 210.76
29	Front Bonnet Hinge RH <i>3</i>	1	\$ 64.89	\$ + 64.89
30	Front Bonnet Hinge LH <i>3</i>	1	\$ 64.89	\$ + 64.89
31	Front Bonnet Latch <i>3</i>	1	\$ 89.97	\$ + 89.97

32	Front Bonnet Lock	1	\$	279.79	\$	+	279.79
33	Front Bonnet Lock Cable	1	\$	31.87	\$	+	31.87
34	Front Fender RH	1	\$	456.99	\$	+	456.99
35	Front Fender Inner Cowling RH	1	\$	107.68	\$	+	107.68
36	Front Fender LH	1	\$	456.99	\$	+	456.99
37	Front Fender Inner Cowling LH	1	\$	107.68	\$	+	107.68
38	Aircon Condenser	1	\$	492.52	\$	+	492.52
39	Radiator Inner	1	\$	812.89	\$	+	812.89
40	Radiator Outer	1	\$	671.17	\$	+	671.17
41	Rear Bumper <i>Dented</i>	1	\$	829.14	\$	✓	829.14
42	Rear Bumper Lower <i>Dented</i>	1	\$	342.86	\$	✓	342.86
43	Rear Bumper Rivets <i>new</i>	4	\$	2.00	\$	✓	8.00
44	Rear Bumper Sensor Bracket RH <i>new</i>	1	\$	16.04	\$	+	16.04
45	Rear Bumper Sensor Bracket LH <i>new</i>	1	\$	16.04	\$	✓	16.04
46	Rear Bumper Sensor RH <i>new</i>	1	\$	189.82	\$	+	189.82
47	Rear Bumper Sensor LH <i>new</i>	1	\$	189.82	\$	✓	189.82
48	Rear Bumper Reinforcement <i>new</i>	1	\$	475.59	\$	+	475.59
49	Rear Bumper Centre Bracket <i>new</i>	1	\$	70.62	\$	✓	70.62
50	Rear Bumper Bracket Upper RH <i>new</i>	1	\$	41.83	\$	+	41.83
51	Rear Bumper Bracket Upper LH <i>new</i>	1	\$	41.83	\$	+	41.83
52	Rear Bumper Bracket Side RH <i>new</i>	1	\$	41.83	\$	+	41.83
53	Rear Bumper Bracket Side LH <i>new</i>	1	\$	41.83	\$	✓	41.83
54	Rear Bumper Reflector RH <i>new</i>	1	\$	78.92	\$	+	78.92
55	Rear Bumper Reflector LH <i>new</i>	1	\$	78.92	\$	✓	78.92
56	Rear Bumper Number Plate Lamp RH <i>new</i>	1	\$	22.14	\$	+	22.14
57	Rear Bumper Number Plate Lamp LH <i>new</i>	1	\$	22.14	\$	+	22.14
58	Rear Tailgate <i>Dented</i>	1	\$	1,562.06	\$	✓	1,562.06
59	Rear Tailgate Mechanism Lock <i>new</i>	1	\$	503.49	\$	+	503.49
60	Rear Tailgate Weatherstrip <i>new</i>	1	\$	337.41	\$	+	337.41
61	Rear Tailgate "Golf" Emblem <i>new</i>	1	\$	86.61	\$	✓	86.61
62	Rear Tailgate Damper RH <i>new</i>	1	\$	117.50	\$	+	117.50
63	Rear Tailgate Damper LH <i>new</i>	1	\$	117.50	\$	+	117.50
64	Rear Tailgate Reflector Lamp RH <i>new</i>	1	\$	385.16	\$	+	385.16
65	Rear Tailgate Reflector Lamp LH <i>new</i>	1	\$	385.16	\$	+	385.16
66	Rear Tailgate Inner Trim Board <i>new</i>	1	\$	528.12	\$	+	528.12
67	Rear Taillamp Assembly RH <i>new</i>	1	\$	585.24	\$	+	585.24
68	Rear Taillamp Assembly LH <i>new</i>	1	\$	585.24	\$	✓	585.24
69	Rear End Panel <i>Dented</i>	1	\$	790.75	\$	✓	790.75
70	Rear End Panel Top Garnish <i>new</i>	1	\$	136.42	\$	+	136.42
71	Rear Spare Tyre Panel Top Cover <i>new</i>	1	\$	375.14	\$	+	375.14
72	Rear Spare Tyre Panel <i>new</i>	1	\$	1,063.14	\$	+	1,063.14
73	Rear Fender RH <i>new</i>	1	\$	1,284.18	\$	+	1,284.18
74	Rear Fender LH <i>Buckled</i>	1	\$	1,284.18	\$	+	1,284.18
75	Rear Fender Inner Cowling RH <i>new</i>	1	\$	107.14	\$	+	107.14

76	Rear Fender Inner Cowling LH <i>from</i>	1	\$	107.14	\$	✓	107.14
77	Rear Fender Inner Trim RH <i>new</i>	1	\$	428.63	\$	+	428.63
78	Rear Fender Inner Trim LH <i>new</i>	1	\$	428.63	\$	+	428.63
79	Rear Exhaust Pipe <i>from</i>	1	\$	1,022.12	\$	+	1,022.12
80	Rear Exhaust Pipe Heat Shield <i>from</i>	1	\$	102.11	\$	+	102.11
81	Rear Exhaust Pipe Mounting	2	\$	24.00	\$	+	48.00
				Parts Sub Total :	\$		29,883.98
				10% Discount	\$		2,988.40
				PARTS TOTAL :	\$		26,895.58

Nos.	SPECIAL NETT	Qty	Unit S\$	TOTAL S\$
1	Front Number Plate <i>Dented</i>	1	\$	50.00
2	Front Bumper Clips - Set <i>from</i>	1	\$	50.00
3	Radiator Grille Clips - Set <i>from</i>	1	\$	50.00
4	Front Bonnet Insulator Clips - Set	1	\$	50.00
5	Front Fender Inner Cowling Clips - Set	1	\$	50.00
6	Front Bonnet Sealant	1	\$	150.00
7	Front Fender RH Sealant	1	\$	150.00
8	Front Fender LH Sealant	1	\$	150.00
9	Coolant <i>new</i>	1	\$	120.00
10	Rear Number Plate <i>new</i>	1	\$	50.00
11	Rear Bumper Clips - Set <i>new</i>	1	\$	50.00
12	Rear Tailgate Inner Trim Board Clips - Set <i>new</i>	1	\$	50.00
13	Rear End Panel Top Garnish Clips - Set	1	\$	50.00
14	Rear Fender Inner Cowling Clips - Set <i>new</i>	1	\$	60.00
15	Rear Fender Inner Trim Clips - Set	1	\$	80.00
16	Rear Tailgate Sealant <i>new</i>	1	\$	150.00
17	Rear End Panel Sealant <i>new</i>	1	\$	150.00
18	Rear Spare Tyre Panel Sealant <i>new</i>	1	\$	150.00
19	Rear Fender RH Sealant <i>new</i>	1	\$	150.00
20	Rear Fender LH Sealant <i>new</i>	1	\$	150.00
21	Rear Tailgate Windscreen Glass Sealant <i>new</i>	1	\$	150.00
22	Rear Bumper Reverse Camera <i>new</i>	1	\$	550.00
SPECIAL NETT TOTAL :				\$ 2,610.00

Nos.	LABOUR	TOTAL S\$
1	To Panel Beat, Remove & Refix Parts (Front)	\$ 600 1,400.00
2	To Panel Beat, Remove & Refix Parts (Rear)	\$ 1200 2,400.00
3	To Spray Paint Affected Areas (Front)	\$ 200 1,200.00
4	To Spray Paint Affected Areas (Rear)	\$ 800 1,800.00
5	Wiring & Bulb Check (Front)	\$ 30 100.00
6	Wiring & Bulb Check (Rear)	\$ 30 100.00
7	To Remove & Refix Front Bumper Sensors	\$ 50 150.00
8	To Remove & Refix Aircon Condenser & Top Up Gas	\$ 60 150.00

9	To Remove & Refix Radiator & Pressure Test	\$	60	150.00
10	To Transfer Rear Tailgate Mechanism	\$	60	150.00
11	To Remove & Refix Rear Bumper Reverse Sensor	\$	50	120.00
12	To Remove & Refix Rear Bumper Reverse Camera	\$	50	150.00
13	To Remove & Refix Rear Tailgate Windscreen Glass	\$	120	150.00
14	To Remove & Refix Rear Exhaust Pipe	\$	X	200.00
15	To Remove & Refix Interior Upholstry to facilitate repairs	\$	60	150.00
16	To Remove & Refix Rear Fuel Tank	\$	X	200.00
17	To Conduct Water Leak Test	\$	X	100.00
18	To apply anti rust on affected parts	\$	80	120.00
19	To Send for Diagnostic and Reset Control Unit. Programming & Calibration	\$	120	480.00
LABOUR TOTAL :		\$		9,270.00

PARTS TOTAL : \$ 26,895.58
 SPECIAL NETT TOTAL : \$ 2,610.00
 LABOUR TOTAL : \$ 9,270.00
GRAND TOTAL : \$ 38,775.58

Advanly
 H/S 13 Days

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

 Acknowledged by Repairer
 Signature:
 Date: