

T K LEE AUTOMOTIVE PTE.LTD

NO 1 KAKI BUKIT AVE 6 #02-47

AUTOBAY SINGAPORE 417883

Tel : 6509 5521 / 65095524 Fax : 6509 5523

The Motor Claims Dept.

INDIA INTERNATIONAL INSURANCE PTE LTD

64 CECIL STREET

#04/#05 IOB BUILDING

SINGAPORE 049711

CB8483R

not Authorized
no
20/11/24
1/5/24 4800
date of the repair
4 days

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before/after spray painting
- To display damaged parts for the survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____
Date: _____

VEHICLE NO : SNK676B
MAKE/MODEL : TOYOTA ALPHARD
ACC DATE : 02.10.2024

PARTICULAR		UNIT PRICE		AMOUNT	
QTY		SS		SS	
LIST PRICE					
1	1 TAILGATE	2,126.20	DO/Bent	2,126.20	✓
2	1 TAILGATE EMBLEM 'ALPHARD'	110.25	neu	110.25	✓
3	1 TAILGATE EMBLEM 'E-FOUR'	89.95	neu	89.95	✓
4	1 TAILGATE EMBLEM 'HYBRID'	89.95	neu	89.95	✓
5	1 TAILGATE GLASS	1,310.59	17	1,310.59	X
6	1 (SET) TAILGATE GLASS MOULDING	182.63	neu	182.63	✓
7	1 TAILGATE INNER LOCK	681.45	SCU	681.45	X
8	1 TAILGATE INNER TRIM BOARD	831.10	17	831.10	X
9	1 TAILGATE W/STRIP	361.43	17	361.43	X
10	2 TAILLAMP LOWER GARNISHES -R/L	481.33	17	962.66	X
11	1 REAR BUMPER	1,366.63	DO/DE	1,366.63	✓
12	2 REAR BUMPER SIDE RETAINERS -R/L	110.25	17	220.50	X
13	2 REAR BUMPER PDC SENSOR	441.33	no/for	882.66	1pc
14	1 REAR END PANEL	971.10	DO/Bent	971.10	✓
15	1 REAR SMART KEYLESS ANTENNA	181.90	17	181.90	X
16	1 REAR SMART KEYLESS BUZZLE	192.60	17	192.60	X
				10,561.60	
LESS 25%				2,640.40	
				7,921.20	

SPECIAL NETT ITEMS

1	1 (SET) TAILGATE GLASS SEALANT	80.00	neu	80.00	40 S/N
2	1 (SET) REAR BUMPER CLIP	50.00	neu	50.00	30 S/N
3	1 REAR BUMPER CHROME PLATE	850.00	DO/Bent	850.00	480 S/N
				980.00	

LABOUR CHARGES :

1	TO REMOVE AND REPLACE REAR TAILGATE GLASS	180.00	120
2	TRANSFER & REINSTALL TAILGATE COMPONENTS TO NEW TAILGATE	150.00	60
3	TO CHECK REAR ELECTRICAL WIRING	50.00	20
4	TO REMOVE & REFIX REAR INTERIOR TRIMS TO ASSIST REPAIR	120.00	80
5	TO TUFF KOTE	80.00	50
6	TO PUTTY, SPRAY PAINT & POLISH AFFECTED PARTS	1,080.00	800
7	TO PANEL BEAT, CUT, WELD, REMOVE & REPLACE DAMAGED PARTS	900.00	600
		2,560.00	

ESTIMATE PARTS AND LABOR GRAND TOTAL :

11,461.20

P-5040.57
252
3780.39
550
1730
6060.39
4800