

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933 TEL: 6256 3561 FAX: 6256 4315 Reg. No: 199607198R GST Reg. No. 19-9607198-R

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SKX 3647H

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	BRAKE & WHEEL ALIGNMENT REPORT FEE		\$75.60	\$75.60
	TO REPAIR AND RESPRAY FRONT BUMPER		\$370.80	\$370.80
	CARS, STATION WAGONS, VANS (MINI BUS, PICK-UPS), JEEPS ETC) SOR 9 COLLECTION @ \$46.12. TO BE CHARGE UNDER MONTHLY SOR (NPA)	NOT NECESSARY	\$0.00	\$0.00
	TO & FRO FOR BRAKE TEST & WHEEL ALIGNMENT REPOATR (MAN HOUR)		\$92.70	\$92.70
				\$539.10
	GRAND TOTAL			\$539.10
	RECOMMENDED COST OF REPAIRS			\$539.10
Report Ref No: CS/FCI24060298/Eqh3e2				

CTY

STEVE CHEN TSUE YEE

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of reposibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.