

BLK 3007 UBI RD 1 #01-408, SINGAPORE 408701

TEL: 6748 8645 FAX: 6748 2533

EMAIL: kivilepc@gmail.com

ROC NO.: 53114844X GST REG NO.: M90370110N

Vehicle No.: FBV9459L model : HONDA WAVE 125

Handle Bar	SU	155	X
Brake Lever	cur	80	—
Balance RH	cur	55	✓
Mirror RH	cur	75	✓
Mudguard	cur	145	—
Brake Paddle	cur	85	✓
Footrest Bar	cur	85	—
Footrest Rubber	Torn	65	—
Rear Footrest RH	cur	85	—
Exhaust Cover	cur	95	—
Starter Switch	M.S	95	✓
Fork	SU	480	X
Fork Lower Clamp	11	280	X
Steering Cone	11	165	X
Exhaust Pipe	Page	580	—
Rear Box	cur	240	200 S/N
Rear Fairer	Painting mudguard	185	X
Rear Body Frame ALIGHTMI	11	450	X
Rear Body Frame Respray	11	350	X
Rear Number Plate	sent	30	
Labour		580	300
Total			

10%

not Authorized
 26/11/24
 2/5 \$1500
 4 days
 the phone 11661
 90086608

1-1630
 102
 1467
 200
 300
 1967
 202
 1543

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: