

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07216

Vehicle Insured : GBJ2901K
Accident Date : 23-Nov-2024

Date : 26-Nov-2024

Our Ref : 024233 (AIG) / CHAN

PAGE : 1

SNG HOCK SIONG
BLK 173 ANG MO KIO AVE 4
#09-711
Singapore 560173

Not Withheld

Permy B4paim

5342.20

4 days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE SNG9595M

- | | |
|-------|------------------------------|
| 1 pc | Rear w/s glass |
| 1 pc | Rear w/s glass moulding |
| 1 pc | Rear wiper motor |
| 1 pc | Rear wiper arm |
| 1 pc | Rear wiper blade |
| 1 pc | Tail gate |
| 1 pc | Tail gate inner lock |
| 1 pc | Tail gate rubber |
| 1 pc | Tail gate inner trim |
| 1 pc | Tail gate open pocket |
| 1 pc | Tail gate outer garnish |
| 2 pcs | Tail gate lamp |
| 1 pc | Tail gate "SHUTTLE" emblem |
| 2 pcs | Tail gate license plate lamp |
| 2 pcs | Taillamp |
| 1 pc | Rear end panel |
| 1 pc | End panel top garnish |
| 1 pc | Rear bumper fascia |
| 1 pc | Rear bumper top chrome |
| 1 pc | Rear bumper tow cover |

disl @ S\$367.50

disl @ S\$135.00
disl @ S\$403.00

<i>Shatter</i>	795.40	✓
<i>re</i>	67.50	✓
<i>re</i>	300.90	✓
<i>re</i>	43.50	✓
<i>re</i>	46.80	✓
<i>re</i>	970.30	✓
<i>re</i>	178.20	✓
<i>disl</i>	117.70	✓
<i>re</i>	194.60	✓
<i>re</i>	16.50	✓
<i>way</i>	372.00	✓
<i>re</i>	735.00	✓
<i>re</i>	49.70	✓
<i>re</i>	270.00	✓
<i>re</i>	806.00	✓
<i>re</i>	444.90	✓
<i>re</i>	90.00	✓
<i>re</i>	864.10	✓
<i>re</i>	76.40	✓
<i>re</i>	16.10	✓

6,455.60

Less 20% : 1,291.12

- | | |
|------|---------------------------------|
| 1 pc | Rear bumper reverse sensor(set) |
| 1 pc | Rear reverse camera |
| 1 pc | Rear bumper clip (set) |

<i>re</i>	5,164.48	✓
<i>re</i>	400.00	sn ✓
<i>re</i>	300.00	sn X
<i>re</i>	30.00	sn ✓

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : GBJ2901K

1 pc Rear no.plate with box

NU 50.00 *435N* sn

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 *120*

To remove roof lining, front and
rear seats, trim board and carpet

150.00 *60*

To apply undersealing

60.00 *30*

To putty and spray replaced parts

1,200.00 *600*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *500*

Total :

S\$ 8,504.48
=====

Singapore Dollars Eight Thousand Five Hundred
and Four and Cents Forty Eight Only