

ASS. REC. BY:

REF:

AIG/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

4.5 days

Res.: Yes or No

Lum Sum:

1.3.1 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Date / Time

Action / Instruction

No 2nd parts, Got BZ

Date/Time, File Pass to?

☐

: Prell. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S - RS. \$

Fees

Others

Add Fee:

☐

: Site Insp (\$

☐

: Interview (\$

☐

: Tech Invs (\$


☐

: Weekend (\$

TOTAL

Report Format:

Lump Sum / I.B.I.: (\$



Veh No: PNG 9595M Yr Regn: 01, 21
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Wagon
 Make: 1 Honda Shuttle cc 1496
 Colour: M. Grey A/C: Insured / Std / NI / NA
 Sp. Reading: 109214 T/Radio: Insured / Std / NI / NA
 Eng/No: _____
 C/No: GK8 . 2101067
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or
 Brake: In order / Jammed / Leaked / Burnt or
 Mod: NI / S/Rim / STD / R/Rim or
 Tyre Size: F: 185/60R15
 R: _____
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 8 mm Rear R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 23/11/2 D.O.I. 26/11/2024
 Survey held at _____
 Des. of Damages: Frit / Rear / O/S / N/S / UIC / Rooftop or
 The U/C / Chassis frame / Body Structure affected due to collision.

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ2901K
Accident Date : 23-Nov-2024

No. : 07216

Date : 26-Nov-2024

Our Ref : 024233 (AIG) / CHAN

PAGE : 1

SNH HOCK SIONG
BLK 173 ANG MO KIO AVE 4
#09-711
Singapore 560173

Not Withheld
Mercury B400M

4-5 days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE SNG9595M

1 pc	Rear w/s glass	<i>Shatter</i>	795.40	✓
1 pc	Rear w/s glass moulding	<i>na</i>	67.50	✓
1 pc	Rear wiper motor		300.90	✓
1 pc	Rear wiper arm	<i>in</i>	43.50	✓
1 pc	Rear wiper blade	<i>in</i>	46.80	✓
1 pc	Tail gate	<i>By</i>	970.30	✓
1 pc	Tail gate inner lock	<i>By</i>	178.20	✓
1 pc	Tail gate rubber		117.70	✓
1 pc	Tail gate inner trim	<i>mycom</i>	194.60	✓
1 pc	Tail gate open pocket	<i>na</i>	16.50	✓
1 pc	Tail gate outer garnish	<i>way</i>	372.00	✓
2 pcs	Tail gate lamp	<i>ol/LRA @ S\$367.50</i>	735.00	✓
1 pc	Tail gate "SHUTTLE" emblem	<i>na</i>	49.70	✓
2 pcs	Tail gate license plate lamp	<i>@ S\$135.00</i>	270.00	✓
2 pcs	Taillamp	<i>ol/LRA @ S\$403.00</i>	806.00	✓
1 pc	Rear end panel		444.90	✓
1 pc	End panel top garnish	<i>na</i>	90.00	✓
1 pc	Rear bumper fascia	<i>By</i>	864.10	✓
1 pc	Rear bumper top chrome	<i>na</i>	76.40	✓
1 pc	Rear bumper tow cover	<i>na</i>	16.10	✓
			6,455.60	
Less 20% :			1,291.12	

- 1 pc Rear bumper reverse sensor(set)
1 pc Rear reverse camera
1 pc Rear bumper clip (set)

5,164.48
400.00 sn 7
300.00 sn X
30.00 sn ✓

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Con't Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Vehicle Insured : GBJ2901K

Page : 2

1 pc Rear no.plate with box	50.00	45.50
To remove & renew rear windscreen glass and conduct water leak test.	150.00	120.00
To remove roof lining, front and rear seats, trim board and carpet	150.00	60.00
To apply undersealing	60.00	?
To putty and spray replaced parts	1,200.00	600.00
To remove, cut-out damaged parts, panel beating, welding, align, refix and to renew above parts	1,000.00	?
Total :	S\$ 8,504.48	

Singapore Dollars Eight Thousand Five Hundred and Four and Cents Forty Eight Only