

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

No. : 07216

Vehicle Insured : GBJ2901K
Accident Date : 23-Nov-2024

Date : 26-Nov-2024

Our Ref : 024233 (AIG) / CHAN

PAGE : 1

SNG HOCK SIONG
BLK 173 ANG MO KIO AVE 4
#09-711
Singapore 560173

Not Withheld

Permy B4Pain

5342.20

4 days

ESTIMATED COST OF REPAIR FOR HONDA SHUTTLE SNG9595M

- | | | |
|-------|------------------------------|---------|
| 1 pc | Rear w/s glass | |
| 1 pc | Rear w/s glass moulding | |
| 1 pc | Rear wiper motor | |
| 1 pc | Rear wiper arm | |
| 1 pc | Rear wiper blade | |
| 1 pc | Tail gate | |
| 1 pc | Tail gate inner lock | |
| 1 pc | Tail gate rubber | |
| 1 pc | Tail gate inner trim | |
| 1 pc | Tail gate open pocket | |
| 1 pc | Tail gate outer garnish | |
| 2 pcs | Tail gate lamp | n/s cru |
| 1 pc | Tail gate "SHUTTLE" emblem | |
| 2 pcs | Tail gate license plate lamp | |
| 2 pcs | Taillamp | |
| 1 pc | Rear end panel | |
| 1 pc | End panel top garnish | |
| 1 pc | Rear bumper fascia | |
| 1 pc | Rear bumper top chrome | |
| 1 pc | Rear bumper tow cover | |

Shatter	795.40	✓
re	67.50	✓
re	300.90	✓
re	43.50	✓
re	46.80	✓
re	970.30	✓
re	178.20	✓
dislrd	117.70	✓
re	194.60	✓
re	16.50	✓
way	372.00	✓
re	735.00	✓
re	49.70	✓
re	270.00	✓
re	806.00	✓
re	444.90	✓
re	90.00	✓
re	864.10	✓
re	76.40	✓
re	16.10	✓

6,455.60

Less 20% : 1,291.12

- | | | |
|------|---------------------------------|--|
| 1 pc | Rear bumper reverse sensor(set) | |
| 1 pc | Rear reverse camera | |
| 1 pc | Rear bumper clip (set) | |

5,164.48	
re	400.00 sn
re	300.00 sn
re	30.00 sn

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Page 2 ...

ALAN'S UNITED AUTO PTE. LTD.

Block 7, Sin Ming Industrial Estate, #01-76, Singapore 575642.

Tel: 6453 8686 (3 Lines) Fax: 6459 6550

Company Reg. No.: 201113667N

GST Reg. No.: 201113667N

Page : 2

Vehicle Insured : GBJ2901K

1 pc Rear no.plate with box

NU 50.00 *435N* sn

To remove & renew rear windscreen
glass and conduct water leak test.

150.00 *120L*

To remove roof lining, front and
rear seats, trim board and carpet

150.00 *60L*

To apply undersealing

60.00 *30L*

To putty and spray replaced parts

1,200.00 *600L*

To remove, cut-out damaged parts,
panel beating, welding, align,
refix and to renew above parts

1,000.00 *500L*

Total :

S\$ 8,504.48
=====

Singapore Dollars Eight Thousand Five Hundred
and Four and Cents Forty Eight Only