

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

DAMAGE ASSESSMENT REPORT						
	INCOME INSURAN	CE LTD		Ref:	CS/INC24110552/Anh3e2(N)	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557			Date:	22/01/2025	
	ATTN: RAJESWAR	Υ		Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SNR 733H	Veh. Inspected	k	SLK 9144J	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	MT/1304964-002	Excess (\$)		0.00	
	Assign From	RAJESWARY	Assign Date		26/11/2024	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA ALTIS	c.c		1598	
	Engine No.	HIDDEN	Year of Reg.		2017	
	Chassis No.	MR053REH104554584	Colour		BROWN	
	Odometer	152887 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/45 R17	MICHELIN		6 mm	
	L/H Front Tyre	215/45 R17	MICHELIN		6 mm	
	R/H Rear Tyre	215/45 R17	MICHELIN		6 mm	
	L/H Rear Tyre	215/45 R17	MICHELIN		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY. DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	09/11/2024	Inspect Date /	Time	02/12/2024 (01:24 PM)	
	Survey held at	MG SOLUTION PTE LTD				
		23 KAKI BUKIT AVE 4 (SOUTH WING) #02-03B VICOM INSPECTION CENTRE, SINGAPORE 415933				
5a.						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 6 Working Days					