

TwinCar AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

TP China
Hui Rong

Contact : 87420435 83187770

TAX INVOICE

Repair Code : CLM16483

Date in : 25/11/2024

Vehicle Num. : SMG4552G

Model : TOYOTA VELLFIRE ELEGANCE MOONROOF (AUTO)

Chassis/Eng# : JTNGF3DH108019538/2ARJ196370

Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
REAR BUMPER <i>Disturbed</i>	1	936.60	✓ 936.60
REAR BUMPER LH UNDER COVER <i>new</i>	1	401.90	+ 401.90
REAR BUMPER REFLECTOR L/R <i>new</i>	2	91.80	750 183.60
REAR BUMPER REVERSE SENSOR <i>2 pieces damaged</i>	4	508.30	1016.60 2,033.20
REAR BUMPER REVERSE SENSOR 'O' RING <i>2 pieces new</i>	4	25.00	50 100.00
REAR BUMPER REVERSE SENSOR HOLDER <i>new</i>	4	38.30	✓ 153.20
REAR BUMPER SIDE RETAINER L/R <i>new</i>	2	149.80	+ 299.60
REAR BUMPER TOW HOOK COVER L/R <i>LH Delivered</i>	2	28.30	28.30 56.60
REAR END PANEL <i>Disturbed</i>	1	1193.30	✓ 1,193.30
REAR END PANEL ANTENNA SENSOR <i>new</i>	1	100.00	+ 100.00
REAR END PANEL INNER TOP GARNISH <i>Delivered</i>	1	231.50	2130 231.50
REAR FENDER INNER TRIM BOARD L/R <i>LH Delivered</i>	2	4079.30	8158.60 8,158.60
REAR FLOOR PANEL <i>Disturbed</i>	1	1245.30	✓ 1,245.30
REAR FLOOR PANEL CARPET MAT <i>new</i>	1	574.70	+ 574.70
REAR FLOOR PANEL SPARE TYRE BRACKET COVER <i>Delivered</i>	1	539.40	✓ 539.40
REAR FLOOR PANEL TOP BOARD COVER (CENTER) <i>new</i>	1	335.10	+ 335.10
REAR FLOOR PANEL TOP BOARD COVER L/R <i>Delivered</i>	2	667.10	✓ 1,334.20
REAR SEAT SLIDING RAIL BRACKET L/R <i>new</i>	2	617.50	X 1,235.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

Contact : 87420435 83187770

TAX INVOICE

Repair Code : CLM16483

Date in : 25/11/2024

Vehicle Num. : SMG4552G

Model : TOYOTA VELLFIRE ELEGANCE MOONROOF (AUTO)

Chassis/Eng# : JTNGF3DH108019538/2ARJ196370

REAR SEAT SLIDING RAIL BRACKET OUTER GARNISH L/R	<i>new</i>	2	195.70	+	391.40
REAR TAILGATE	<i>Deled</i>	1	3113.60	<i>2920</i>	3,113.60
REAR TAILGATE 'VELLFIRE' EMBLEM	<i>new</i>	1	94.10	+	94.10
REAR TAILGATE AUTO SENSOR L/R	<i>new</i>	2	1211.10	+	2,422.20
REAR TAILGATE DAMPER L/R	<i>new</i>	2	485.90	+	971.80
REAR TAILGATE HINGES L/R	<i>new</i>	2	104.00	+	208.00
REAR TAILGATE INNER TRIM BOARD	<i>Deled</i>	1	1138.30	<i>959</i>	1,138.30
REAR TAILGATE MECHANISM LOCK	<i>Deled</i>	1	1207.10	<i>850</i>	1,207.10
REAR TAILGATE MECHANISM LOCK MOTOR	<i>new</i>	1	3898.30	+	3,898.30
REAR TAILGATE OUTER GARNISH	<i>cut</i>	1	1451.50	-	1,451.50
REAR TAILGATE OUTER GARNISH 'LOGO' EMBLEM	<i>new</i>	1	100.20	-	100.20
REAR TAILGATE REFLECTOR L/R	<i>cut</i>	2	1642.20	-	3,284.40
REAR TAILGATE REVERSE CAMERA	<i>new</i>	1	1935.70	+	1,935.70
REAR TAILGATE WEATHER STRIP	<i>lt</i>	1	515.40	-	515.40
REAR TAILGATE WINDSCREEN MOULDING	<i>new</i>	1	113.20	-	113.20
REAR TAILLAMP L/R	<i>cut</i>	2	1233.20	-	2,466.40
REAR TAILLAMP LOWER GARNISH L/R	<i>tern</i>	2	401.90	-	803.80
REAR TAILLAMP LOWER GARNISH RETAINER L/R	<i>new</i>	2	157.10	+	314.20

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

Contact : 87420435 83187770

TAX INVOICE

Repair Code : CLM16483

Date in : 25/11/2024

Vehicle Num. : SMG4552G

Model : TOYOTA VELLFIRE ELEGANCE MOONROOF (AUTO)

Chassis/Eng# : JTNGF3DH108019538/2ARJ196370

		Subtotal before discount	20438.50	43,541.40
Percentage discount 25%			15328.875	10,885.35
		Sub-total 1		32,656.05
REAR BUMPER CLIPS - SET <i>mw</i>	1	50.00	30	50.00
REAR END PANEL INNER TOP GARNISH CLIPS - SET <i>mw</i>	1	30.00	20	30.00
REAR FENDER INNER TRIM BOARD CLIPS L/R - SET <i>mw</i>	2	50.00	30	100.00
REAR TAILGATE INNER TRIM BOARD CLIPS - SET <i>mw</i>	1	50.00	30	50.00
REAR TAILGATE NUMBER PLATE <i>mw</i>	1	25.00	+	25.00
REAR TAILGATE NUMBER PLATE FRAME <i>mw</i>	1	50.00	+	50.00
REAR TAILGATE OUTER GARNISH CLIPS - SET <i>mw</i>	1	30.00	20	30.00
REAR TAILGATE WINDSCREEN SEALANT <i>mw</i>	1	80.00	60	80.00
		Subtotal before discount		415.00
Percentage discount 0%				0.00
		Sub-total 2		415.00
		Parts-total		33,071.05

LABOUR

To remove, reinstall electrical wiring harness, check lighting and rewire for parking sensor.

To remove, reinstall tailgate windscreen

To remove, reinstall roof top trim upholstery, cushion seat, trim garnish, trim liner carpet. (to FR)

✓ 80.00
120 180.00
60 80.00

*** This is a computer-generated document which requires no signature.***

Kaki Bukit AutoHub
2 Kaki Bukit Ave 2
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510
E-Mail : sales@n51.com.sg
Company Reg. No. : 200714616M
GST Registration No. : 200714616M

ROSET LIMOUSINE SERVICES PTE LTD
53 UBI AVE 1 #03-47 PAYA UBI IND PARK
SINGAPORE 408934

Contact : 87420435 83187770

TAX INVOICE

Repair Code : CLM16483

Date in : 25/11/2024

Vehicle Num. : SMG4552G

Model : TOYOTA VELLFIRE ELEGANCE MOONROOF (AUTO)

Chassis/Eng# : JTNGF3DH108019538/2ARJ196370

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

To remove, reinstall tailgate mechanism and check for function

~~1800~~ 1,400.00
2600 1200 1,400.00
80 120.00
60 80.00

Labour Total

3,340.00

Parts & Labour Total

36,411.05

*** This is a computer-generated document which requires no signature.***

page 4

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Admin L
h/s 26/11/24
09 Days

total: 18118.875
h/s: 14.5k

14.5k