

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@proccarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

MS FIRST CAPITAL INSURANCE LIMITED

6 Raffles Quay

#21-00

Singapore 048580

Tel: 62222311

Fax: 62223547

Attn: Motor Claim Department

Your Ref No: TP 1124-8372

Claim Type: Third Party

Accident Date: 24 November 2024

TP Veh Reg No: SHB3019Y

Estimate No: EST1512074

Date: 25 Nov 2024

Policy No: P10924515R01

Veh Reg No: SLP5512E

Make/Model: MINI MINI COOPER S
COUNTRYMAN LED NAV

Chassis No: WMWYS920403E09521

Engine No: F239H476B48A20A

Reg. Date: 09 Jun 2017

Estimate Repair Cost to Vehicle No: SLP5512E

Description	Unit Price	Quantity	List Price SGD	Amount SGD
List Price				
1 REAR BUMPER-	2,004.75	1 PC	2,004.75	
2 REAR BUMPER CORNER - LH	165.95	1 PC	165.95	
3 REAR BUMPER SIDE RETAINER - LH/RH-	297.00	2 PC	594.00	
4 REAR BUMPER CLIPS-	4.00	10 PC	40.00	
5 REAR BUMPER LOWER (MATT BLACK)-	445.50	1 PC	445.50	
6 REAR BUMPER CENTER LOWER (GLOSS BLACK GARNISH)	288.42	1 PC	288.42	
7 REAR BUMPER SENSOR	289.95	2 PC	579.90	
8 REAR BUMPER SENSOR RING	11.50	4 PC	46.00	
9 REAR BUMPER SENSOR WIRE	1,328.30	1 PC	1,328.30	
10 REAR BUMPER REFLECTOR - LH	50.50	1 PC	50.50	
11 REAR BUMPER INNER MOUNT BRACKET - LH-	0.00	1 PC	0.00	
12 REAR BUMPER REINFORCEMENT	607.52	1 PC	607.52	
13 REAR EXHAUST	1,481.72	1 PC	1,481.72	
14 REAR EXHAUST REPAIR KIT	100.50	1 PC	100.50	
15 REAR EXHAUST CHROME - LH-	157.80	1 PC	157.80	
16 REAR EXHASUT TOP MOUNTING - LH-	39.20	1 PC	39.20	
17 REAR SMART OPENER MOUNTING BRACKET-	114.40	1 PC	114.40	
18 REAR FENDER - LH	4,154.40	1 PC	4,154.40	
19 REAR FENDER COWLING - LH-	187.24	1 PC	187.24	
20 REAR FENDER COWLING CLIPS - LH	4.00	10 PC	40.00	
21 REAR FENDER INNER AIR VENT - LH-	55.60	1 PC	55.60	
22 TAIL LAMP - LH-	415.80	1 PC	415.80	
23 TAILGATE "COOPER S" WORDINGS-	89.50	1 PC	89.50	
24 TAILGATE "COUNTRYMAN" WORDINGS-	100.50	1 PC	100.50	
			13,087.50	
		Less 10%	-1,308.74	11,778.76

Labour				
25 TO KNOCK OUT DENTS ON END PANEL, CUT/WELD REAR FENDER LH, REMOVE, REPLACE ACCIDENT PORTIONS-	1,000.00	1 JOB	1,000.00	
26 TO RESPRAY PAINT ON ACCIDENT PORTIONS (PEARL)-	900.00	1 JOB	900.00	
27 TO CHECK WIRING-	30.00	1 JOB	30.00	
28 TO REMOVE, REFIT GARNISH TO FACILITATE REPAIR-	150.00	1 JOB	150.00	
29 TO REMOVE, REPLACE REAR BUMPER SENSOR-	80.00	1 JOB	80.00	
30 TO DIAGNOSE & RESET DTC-	200.00	1 JOB	200.00	
31 TO ANTI RUST-	80.00	1 JOB	80.00	

2,440.00

Progressive Car Care Pte Ltd

Blk 3022A Ubi Road 1 #01-45/46 Singapore 408716

TEL: 6741 5336 FAX: 6741 7208

Email: claims@procarcare.com.sg

GST REG NO: 201006949C Company Reg No: 201006949C

Total	14,218.76
Add GST @ 9%	1,279.69
Total Amount Payable SGD	15,498.45

SINGAPORE DOLLAR FIFTEEN THOUSAND FOUR HUNDRED NINETY EIGHT AND CENTS FORTY FIVE ONLY

For Progressive Car Care Pte Ltd



AUTHORISED SIGNATURE