



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

LONPAC INSURANCE BHD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555
ATTN: Jasmine Lok

INV No. AC2600798
INV Date 30/01/2026
Reference CD/LPC24110560/Rpa3q2
Code LPC2

PROFESSIONAL SERVICE FEE

Vehicle No. PC 8628G
Insured Veh. YP 8952U
Claim No. 24/24/24/VC05/030227
Policy No. Z24VC05025018
Accident Date 18/10/2024
Inspection Date 28/11/2024

Description	Total
Third Party Express Settlement	450.00
Subtotal	450.00
GST (9%)	40.50
Grand Total	490.50

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

LKM



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSE SINGAPORE 199555 ATTN: Jasmine Lok		Ref: CD/LPC24110560/Rpa3q2(N) Date: 30/01/2026 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	YP 8952U	Veh. Inspected	PC 8628G
Policy No.	Z24VC05025018	Coverage (\$)	0.00
Claim No.	24/24/24/VC05/030227	Excess (\$)	0.00
Assign From	GERALD POH	Assign Date	28/11/2024
2. Vehicle Particulars & Condition			
Make & Model	KING LONG XMQ6117K5	c.c	6691
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	LA6R1FSH2HB402229	Colour	MULTI COLOUR
Odometer	378725 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	FAIR		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	11 R22.5	ARISUN	8 mm
L/H Front Tyre	11 R22.5	ARISUN	8 mm
R/H Rear Tyre	11 R22.5 (D)	ARISUN	8/8 mm
L/H Rear Tyre	11 R22.5 (D)	ARISUN	8/8 mm
4. Description of Damages			
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.		
5. General Information			
Accident Date	18/10/2024	Inspection Date	28/11/2024
Survey held at	ONE LINE MOTORWORKS TRADING 11 TUAS BAY CLOSE, WEST STAR #06-03 SINGAPORE 636996		
5a. Remarks			
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.		
5b. Estimate Days of Repair			
	ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. PC 8628G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	LUGGAGE COMPARTMENT	BENT	1,565.89	1,565.89
1	REAR R WHEEL PANEL	BENT	2,315.48	2,315.48
1	WEATHERSTRIP 12M	CUT	879.65	879.65
4	GAS SPRING	SERVICEABLE	894.52	-
	LESS 10% DISCOUNT		-	-476.10
			5,655.54	4,284.92
<u>LABOUR</u>				
	TO SUPPLY PANEL BEATERS TO REPLACE /JACK/REALIGN SIDE PANEL .		2,800.00	1,400.00
	TO SUPPLY ELECTRICIANS TO REPLACE /JACK/REALIGN LUGGAGE COMPARTMENT.		1,400.00	420.00
	TO SUPPLY PANEL BEATERS TO REPLACE /JACK/REALIGN REAR R WHEEL PANEL.		700.00	280.00
	TO SUPPLY PANEL BEATERS TO REPLACE WEATHERSTRIP .		350.00	140.00
	TO SPRAY PAINT MULTIPLE COLOURS AFFECTED PANELS.		8,000.00	1,750.00
			13,250.00	3,990.00
GRAND TOTAL			18,905.54	8,274.92
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				6,600.00

Report Ref No. CD/LPC24110560/Rpa3q2(N)

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.

PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

INSPECTION PHOTOS (Page 3 of 8)

PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G



PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G





LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933
TEL: 6256 3561 FAX: 6256 4315
Reg. No: 199607198R GST Reg. No.
19-9607198-R

REINSPECTION PHOTOS (Page 1 of 1)

PHOTOGRAPHS FOR VEHICLE NO. : PC 8628G

