

One Line Motorworks Trading

11, Tuas Bay Close #06-03 West Star, Singapore 636996

Tel: 62622106

Company Reg No: 53375959E

Email: tricia.onelinemotorworks@gmail.com

28TH November 2024

BY HAND

THIRD-PARTY CLAIM YP8952U- REPAIR ESTIMATE FOR PC8628G

TRAFFIC ACCIDENT ON 18/10/24, TRAFFIC ACCIDENT Near 504 Old Choa Chu Kang Rd, Singapore 698922, INSIDE HOME TEAM ACADEMY

To whomever it concerns,

We append below our repair estimate for PC8628G

Repair Estimate

Parts required:

1. Luggage Compartment	4761.02	\$	1565.89
2. Rear R Wheel Panel	10%	\$	2315.48
3. Weatherstrip 12m		\$	879.65
4. Gas Spring 4pcs	4284.91	\$	894.52 X

Labour charges:

1. To supply panel beaters to replace/jack/realign side panel	280 \$350 x 8 Day(s)	\$	2800.00 1400
2. To supply electricians to replace/jack/realign luggage compartment	280 \$350 x 4 Day(s)	\$	1400.00 820
3. To supply panel beaters to replace/jack/realign rear R wheel Panel	280 \$350 x 2 Day(s)	\$	700.00 280
4. To supply panel beaters to replace weatherstrip	280 \$350 x 1 Day(s)	\$	350.00 140
5. To spray paint multiple colours affected panels	\$800/panel 350 X 5	\$	8000.00 1750

Total repair costs:

4284.91

3990.00

8274.91

20%

6619.92

\$ 18,905.54

L/S - \$6,600 / 7 days

This estimate is based on visible damage only. Should any hidden parts and/or labour required during works in progress, insurer and/or their surveyor will be notified accordingly.

Mrs Say Pheng
(HP: 9797 1868)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Case
Up 90010068

7 days

L/S

28/11/24

Reg after repair