

ASS. REC. BY:

REF:

CS/SMR24060300/Kvh3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured: SHF 48L

Policy No.

Claims No. TAX/06/24/2071

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Colour

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I: (\$

Days Of Repair: 7

Resurvey No. of Trip:

Add Fee:

Site Insp (\$

Interview (\$

Tech Invs (\$

Weekend (\$

Survey Fee:

Transportation

S + RS. SI

Fees

Others

TOTAL

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

Date : 26 / 06 / 2024

ESTIMATE COSTS OF REPAIR

Mr. Wong Hoy Kim

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not within
11 days & 8000/-
Return After 10 days
7 days*

Dear Sir / Madam,

Vehicle no. : SDZ 9988 G - Toyota Harrier M Grade
Accident date : 25 / 06 / 2024

Quantity	Descriptions	Amount (S\$)
1	1 pc n/s side mirror	<i>Ref/Ins</i> 1,037.00 ✓
2	1 pc n/s side mirror cover	\$ <i>Ref</i> 89.50 ✓
3	1 pc n/s front door	\$ <i>Ref</i> 1,460.00 ✓
4	2 pcs n/s front door hinge 1 @ 87.20	\$ <i>R</i> 174.40 X
5	1 pc n/s front door checker	\$ <i>Ins</i> 195.00 X
6	1 pc n/s front door frame black sticker 125	\$ <i>Ref</i> 297.00 ✓
7	1 pc n/s front door inner trim board 1420	<i>Ref</i> \$ <i>Ref</i> 2,228.00 ✓
8	1 pc n/s front door inner lock	\$ <i>Ref</i> 426.30 ✓
9	1 pc n/s front door rubber	\$ <i>Ins</i> 163.80 X
10	1 pc n/s front door outer moulding	\$ <i>Ref</i> 130.70 ✓
11	1 pc n/s front door moulding (lower)	\$ <i>Ref</i> 219.00 ✓
12	1 pc n/s front door outer handle	\$ <i>Ref/Ins</i> 361.74 ✓
13	1 pc n/s front door outer handle cover	\$ <i>Ref</i> 79.26 ✓
14	1 pc n/s front door outer handle frame	\$ <i>Ref</i> 238.17 ✓
15	2 pcs n/s front door outer handle pad 1 @ 41.92	\$ <i>Ref</i> 83.84 ✓
16	1 pc n/s front door glass regulator gear	\$ <i>Ref</i> 209.60 ✓
17	1 pc n/s front door glass regulator gear motor	\$ <i>Ref</i> 559.20 ✓
18	1 pc n/s rear door	\$ <i>Ref</i> 1,619.00 ✓
19	1 pc n/s rear door rubber	\$ <i>Ref</i> 180.00 X
20	1 pc n/s rear door glass outer molding	\$ <i>Ref</i> 125.70 X
21	1 pc n/s rear door outer molding (lower)	\$ <i>Ref</i> 127.14 ✓
22	1 pc n/s rear door outer handle	\$ <i>Ref</i> 139.88 ✓
23	1 pc n/s rear door outer handle cover	\$ <i>Ref</i> 79.17 X
24	1 pc n/s rear door outer handle frame	\$ <i>Ref</i> 238.17 X
25	2 pcs n/s rear door outer handle pad 1 @ 41.92	\$ <i>Ref</i> 83.84 X
26	1 pc n/s rear door glass regulator gear	\$ <i>Ref</i> 198.26 X
27	1 pc n/s rear door glass regulator gear motor	\$ <i>Ref</i> 719.38 X
28	1 pc n/s rear door inner trim board	\$ <i>Ref</i> 1,519.98 X
Balance C/FD		\$ 12,983.03

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

Balance B/FD (SDZ 9988 G)

\$ 12,983.03

29	1 pc	n/s rear fender
30	1 pc	n/s rear fender inner garnish
31	1 pc	n/s rear fuel tank cap
32	1 pc	rear bumper fascia
33	1 pc	n/s tail lamps 581-90
34	1 pc	n/s tail lamps lower bracket

\$ 1,291.84 ✓
\$ 605.20 X
\$ 84.76 X
\$ 1,712.00 X
\$ 731.94 ✓
\$ 128.00 X

Less 25 %

\$ 17,536.77

Balance C/FD

\$ 4,384.19

\$ 13,152.58

35	1 pc	rear quarter glass inner seal
36	1 pc	rear quarter glass inner gum

\$ 120.00 sn 305M ✓
\$ 120.00 sn 405M ✓

Balance C/FD

\$ 13,392.58

Labour charges

\$ 1,800.00 90d

To putty and spray painting

\$ 1,600.00 110d

Refix & remove bumper sensor

\$ 150.00 X

To check wiring, diagnostic, clear fault code, repair wiring

\$ 350.00 20d

Remove and refix rear quarter glass

\$ 180.00 80d

Remove and refix fuel tank pipe

\$ 180.00 60d

Remove and refix chushion seat, carpet, garnish

\$ 280.00 100d

To re-seal anti rust

\$ 300.00 90d

Plus : 9 % GST

\$ 18,232.58

Sub_Total

\$ 1,640.93

\$ 19,873.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: