

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

Date : 26 / 06 / 2024

ESTIMATE COSTS OF REPAIR

Mr. Wong Hoy Kim

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

*Not within
1/1m & 8000/-
Repair After Rain
7 days*

Dear Sir / Madam,

Vehicle no. : SDZ 9988 G - Toyota Harrier M Grade

Accident date : 25 / 06 / 2024

Quantity	Descriptions	Amount (S\$)
1	1 pc n/s side mirror	<i>Ref/Ins</i> 1,037.00 ✓
2	1 pc n/s side mirror cover	\$ <i>Ref</i> 89.50 ✓
3	1 pc n/s front door	\$ <i>By</i> 1,460.00 ✓
4	2 pcs n/s front door hinge 1 @ 87.20	\$ <i>R</i> 174.40 X
5	1 pc n/s front door checker	\$ <i>In</i> 195.00 X
6	1 pc n/s front door frame black sticker <i>125</i>	\$ <i>Me</i> 297.00 ✓
7	1 pc n/s front door inner trim board <i>1420</i>	<i>mg</i> \$ <i>Ref</i> 2,228.00 ✓
8	1 pc n/s front door inner lock	\$ <i>Ref</i> 426.30 ✓
9	1 pc n/s front door rubber	\$ <i>In</i> 163.80 X
10	1 pc n/s front door outer moulding	\$ <i>By</i> 130.70 ✓
11	1 pc n/s front door moulding (lower)	\$ <i>Me</i> 219.00 ✓
12	1 pc n/s front door outer handle	\$ <i>Ref/Ins</i> 361.74 ✓
13	1 pc n/s front door outer handle cover	\$ <i>Ref</i> 79.26 ✓
14	1 pc n/s front door outer handle frame	\$ <i>CR</i> 238.17 ✓
15	2 pcs n/s front door outer handle pad 1 @ 41.92	\$ <i>Me</i> 83.84 ✓
16	1 pc n/s front door glass regulator gear	\$ <i>By</i> 209.60 ✓
17	1 pc n/s front door glass regulator gear motor	\$ <i>In</i> 559.20 ✓
18	1 pc n/s rear door	\$ <i>By</i> 1,619.00 ✓
19	1 pc n/s rear door rubber	\$ <i>In</i> 180.00 X
20	1 pc n/s rear door glass outer molding	\$ <i>In</i> 125.70 X
21	1 pc n/s rear door outer molding (lower)	\$ <i>Me</i> 127.14 ✓
22	1 pc n/s rear door outer handle	\$ <i>In</i> 139.88 ✓
23	1 pc n/s rear door outer handle cover	\$ <i>In</i> 79.17 X
24	1 pc n/s rear door outer handle frame	\$ <i>In</i> 238.17 X
25	2 pcs n/s rear door outer handle pad 1 @ 41.92	\$ <i>In</i> 83.84 X
26	1 pc n/s rear door glass regulator gear	\$ <i>In</i> 198.26 X
27	1 pc n/s rear door glass regulator gear motor	\$ <i>In</i> 719.38 X
28	1 pc n/s rear door inner trim board	\$ <i>In</i> 1,519.98 X
	Balance C/FD	\$ 12,983.03

H C AUTO PTE LTD

160 Sin Ming Drive # 05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 20082 0153N

Balance B/FD (SDZ 9988 G)

\$ 12,983.03

29	1 pc	n/s rear fender
30	1 pc	n/s rear fender inner garnish
31	1 pc	n/s rear fuel tank cap
32	1 pc	rear bumper fascia
33	1 pc	n/s tail lamps 581-90
34	1 pc	n/s tail lamps lower bracket

\$ 1,291.84 ✓
 \$ 605.20 X
 \$ 84.76 X
 \$ 1,712.00 X
 \$ 731.94 ✓
 \$ 128.00 X

\$ 17,536.77

Less 25 %

\$ 4,384.19

Balance C/FD

\$ 13,152.58

35	1 pc	rear quarter glass inner seal
36	1 pc	rear quarter glass inner gum

\$ 120.00 sn 30sn ✓
 \$ 120.00 sn 40sn ✓

\$ 13,392.58

Labour charges

\$ 1,800.00 900

To putty and spray painting

\$ 1,600.00 1100

Refix & remove bumper sensor

\$ 150.00 X

To check wiring, diagnostic, clear fault code, repair wiring

\$ 350.00 200

Remove and refix rear quarter glass

\$ 180.00 800

Remove and refix fuel tank pipe

\$ 180.00 600

Remove and refix chushion seat, carpet, garnish

\$ 280.00 1000

To re-seal anti rust

\$ 300.00 900

\$ 18,232.58

Plus : 9 % GST

\$ 1,640.93

Sub_Total

\$ 19,873.51

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: