



進友成汽車服務私人有限公司
CYS Automobile Services Pte Ltd

ROC Reg. No :A05041/2001E

GST Reg. NO: 20-0105041-E

INSURER:

ECICS Limited (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	OD 3975
Policy No:	MPC24P00285500	Date of Loss:	24/11/2024
Vehicle Reg. No.:	SMM1974E	Driveable?	
Driver Age/Info:	60 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	HARIZ MUHAMAD SYAHMI	Contact No:	+6598571287
Driver:	HARIZ MUHAMAD SYAHMI		
Make/Model:	BMW X3 XDRIVE30I, 2.0 LED NAV HUD MSPT (A)	Vehicle Reg. Date:	26/07/2019
Vehicle Colour:	Grey		
Engine No:	H3883309B48B20B	Chassis No:	WBATR92030LE27126
Odometer:	138881 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	12		

Description of Accident/Loss ON THE ABOVE-MENTIONED DATE & TIME, I WAS TRAVELLING ALONG
PAYA LEBAR FLYOVER EUNOS. VEHICLE B IN FRONT OF ME JAMMED BRAKE. I
COULDN'T BRAKE IN TIME AND COLLIDED ONTO VEHICLE B REAR PORTION.

Present Location: CYS AUTOMOBILE SERVICES PTE LTD (WOODLANDS)

COST OF CLAIMS	Amount
Parts	16,109.50
Miscellaneous Items	55.00
Labour	1,420.00
Paintwork Labour	0.00
Towing	0.00
Calculated Gross Total (S\$)	17,584.50
- Excess (S\$)	500.00
(S\$)	17,084.50
+ GST 9.00% (S\$)	1,537.61
Nett Amount (S\$)	18,622.11

This claim is handled by: TEE WEE SIN

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2024)
 Parts: M1-SUV BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	*2,200.00 F <i>bb</i>
2	1		*BONNET EMBLEM	0.00	0.00	*85.00 F <i>ne</i>
3	2		*BONNET LOCK	0.00	0.00	*260.00 F ?
4	1		*BONNET LOCK PASSIVE WITH SWITCH	0.00	0.00	*90.00 F <i>x</i>
5	1		*FRONT GRILLE BASE	0.00	0.00	*390.00 F ?
6	2		*FRONT GRILLE CHROME	0.00	0.00	*280.00 F <i>de</i>
7	1		*FRONT GRILLE AIR FLAP CONTROL	0.00	0.00	*120.00 F ?
8	1		*FRONT BUMPER	0.00	0.00	*1,800.00 F <i>de</i>
9	1		*FRONT BUMPER REINFORCEMENT UPPER	0.00	0.00	*980.00 F ?
10	1		*FRONT BUMPER REINFORCEMENT LOWER	0.00	0.00	*420.00 F ?
11	1		*FRONT BUMPER SPONGE	0.00	0.00	*90.00 F ?
12	2		*FRONT BUMPER FOG LAMP	<i>RHx</i> 0.00	0.00	*1,100.00 F <i>LH-?</i>
13	2		*FRONT BUMPER FOG LAMP GARNISH	<i>RHy</i> 0.00	0.00	*280.00 F <i>LH-?</i>
14	1		*FRONT BUMPER CENTRE GARNISH	0.00	0.00	*250.00 F <i>de</i>
15	1		*FRONT BUMPER NUMBER PLATE GARNISH	0.00	0.00	*110.00 F <i>de</i>
16	1		*FRONT BUMPER TOWING COVER	0.00	0.00	*60.00 F <i>mis</i>
17	1		*FRONT BUMPER CAMERA	0.00	0.00	*780.00 F ?
18	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*190.00 F ?
19	<i>32</i>		*FRONT BUMPER PARKING SENSOR	0.00	0.00	*1,440.00 F ?
20	2		*FRONT BUMPER PARKING SENSOR BRACKET	0.00	0.00	*300.00 F <i>ne</i>
21	1		*FRONT SUPPORT PANEL	0.00	0.00	*350.00 F ?
22	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	*280.00 F <i>ne</i>
23	1		*AIR-CON CONDENSER	0.00	0.00	*1,190.00 F ?
24	1		*RADIATOR 1	0.00	0.00	*850.00 F ?
25	1		*RADIATOR 2	0.00	0.00	*750.00 F ?

F=Franchise part.

Sub Total (\$\$)	14,645.00
+ Margin on L,N Items 10.00% (\$\$)	1,464.50
Total Parts (\$\$)	16,109.50

CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			20.00 <i>key</i>
1	4	FRONT BUMPER CLIPS	35.00 <i>66</i>
2	1	FRONT NUMBER PLATE	
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE AND REFIX FRONT PARKING SENSOR & CHECK WIRING FUNCTION	New	50.00 <i>✓</i>
2	TO REMOVE AIR-CON CONDENSER, PIPE, DRIER & TOP-UP AIR-CON GAS	New	120.00 <i>?</i>
3	LABOUR CHARGE FOR REMOVING, REFITTING AND REPAIRING OF AFFECTED ACCIDENT PARTS	New	650.00 <i>450</i>
4	TO PUTTY AND SPRAY PAINTING CHARGES	New	600.00 <i>500</i>
Gross Labour Cost (S\$)			1,420.00

CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, Singapore 757700
Tel: 6219 2098 (3 lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Tanpin 97495749

Not Authorise 27/11/24R 240pm.

Ex: to be advise

tanpin e/khauto.com

c/s Resurvey after repair

4 days

Reference

Parts: M1-SUV BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)

Print Code: **CYS Automobile Services Pte Ltd/SMM1974E/27/11/2024 14:44**

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*HEADLAMP ASY	0.00	0.00	*9,000.00 F
			F=Franchise part.			
			Sub Total (S\$)			9,000.00
			+ Margin on L,N Items 10.00% (S\$)			900.00
			Total Parts (S\$)			9,900.00

F=Franchise part.

CYS Automobile Services Pte Ltd/SMM1974E/27/11/2024 14:44. Not valid without Reference section.
Generated using Merimen e-Claims IEAS