

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 27 Nov 2024)
Parts: M1-SUV BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: CYS Automobile Services Pte Ltd/SMM1974E/27/11/2024 14:44
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	2		*HEADLAMP ASY	0.00	0.00	*9,000.00 F
				4000		9,000.00
						900.00
						9,900.00

CYS Automobile Services Pte Ltd/SMM1974E/27/11/2024 14:44. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

4000
 +10%- 4400

LXXXXX

XXXXX

XXXXXX

\$ XXXXXXXXXXXXXXX

LS 2 XXXXXXXXXXXXXXX
 2

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Nov 2024)
 Parts: M1-SUV BMW X3 XDRIVE30I 2.0 LED NAV HUD MSPT (A) (Catalogue:Merimen Singapore 1.0)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET	0.00	0.00	1950*2,200.00 F <i>bb</i>
2	1		*BONNET EMBLEM	0.00	0.00	*85.00 F <i>ne</i>
3	2		*BONNET LOCK	0.00	0.00	*260.00 F <i>nn</i>
4	1		*BONNET LOCK PASSIVE WITH SWITCH	0.00	0.00	*90.00 F <i>nn</i>
5	1		*FRONT GRILLE BASE	0.00	0.00	*390.00 F <i>cur</i>
6	2		*FRONT GRILLE CHROME	0.00	0.00	*280.00 F <i>de</i>
7	1		*FRONT GRILLE AIR FLAP CONTROL	0.00	0.00	*120.00 F <i>dis</i>
8	1		*FRONT BUMPER	0.00	0.00	1600*1,800.00 F <i>de</i>
9	1		*FRONT BUMPER REINFORCEMENT UPPER	0.00	0.00	*980.00 F <i>bt</i>
10	1		*FRONT BUMPER REINFORCEMENT LOWER	0.00	0.00	*420.00 F <i>nn</i>
11	1		*FRONT BUMPER SPONGE	0.00	0.00	*90.00 F <i>nn</i>
12	2		*FRONT BUMPER FOG LAMP	<i>RH</i> 0.00	0.00	*1,400.00 F <i>nn</i>
13	2		*FRONT BUMPER FOG LAMP GARNISH	<i>RH</i> 0.00	0.00	*280.00 F <i>nn</i>
14	1		*FRONT BUMPER CENTRE GARNISH	0.00	0.00	*250.00 F <i>de</i>
15	1		*FRONT BUMPER NUMBER PLATE GARNISH	0.00	0.00	*110.00 F <i>de</i>
16	1		*FRONT BUMPER TOWING COVER	0.00	0.00	*60.00 F <i>mis</i>
17	1		*FRONT BUMPER CAMERA	0.00	0.00	580 *780.00 F <i>dis</i>
18	1		*FRONT BUMPER LOWER GRILLE	0.00	0.00	*190.00 F <i>de</i>
19	<i>32</i>		*FRONT BUMPER PARKING SENSOR <i>(80 x 2 = 160)</i>	0.00	0.00	*1,440.00 F <i>nn</i>
20	2		*FRONT BUMPER PARKING SENSOR BRACKET	0.00	0.00	150 *300.00 F <i>nn</i>
21	1		*FRONT SUPPORT PANEL	0.00	0.00	*350.00 F <i>nn</i>
22	1		*FRONT SUPPORT PANEL TOP GARNISH	0.00	0.00	*280.00 F <i>nn</i>
23	1		*AIR-CON CONDENSER	0.00	0.00	*1,490.00 F <i>nn</i>
24	1		*RADIATOR 1	0.00	0.00	*850.00 F <i>nn</i>
25	1		*RADIATOR 2	0.00	0.00	*750.00 F <i>nn</i>

F=Franchise part.

Sub Total (\$\$) 14,645.00
 + Margin on L,N Items 10.00% (\$\$) 1,464.50
 Total Parts (\$\$) 16,109.50

CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

7985
 +10% - 8783.50

XXXXXXXX

XXXXXXXX

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	4	FRONT BUMPER CLIPS	20.00 <i>key</i>
2	1	FRONT NUMBER PLATE	35.00 <i>66</i>
Sub Total (S\$)			55.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISMANTLE AND REFIX FRONT PARKING SENSOR & CHECK WIRING FUNCTION	New	50.00 ✓
2	TO REMOVE AIR-CON CONDENSER, PIPE, DRIER & TOP-UP AIR-CON GAS	New	120.00 <i>nn</i>
3	LABOUR CHARGE FOR REMOVING, REFITTING AND REPAIRING OF AFFECTED ACCIDENT PARTS	New	650.00 <i>450</i>
4	TO PUTTY AND SPRAY PAINTING CHARGES	New	600.00 <i>500</i>
Gross Labour Cost (S\$)			1,420.00

CYS Automobile Services Pte Ltd/SMM1974E/26/11/2024 14:12. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

38 Woodlands Industrial Park East 1, #07-17, Admiralty Industrial Park, Singapore 757700
Tel: 6219 2098 (3 lines) Fax: 6219 2096 E-mail: cysauto@singnet.com.sg

4400
8783.50
55
1000
14238.50
LS \$11400
4 DAYS #

Taufik 97495749

Not Authorise 27/11/24 24 Apr.

Ex: to be advise

taufik e/khaufo.com

c/s Resurvey after repair

4 days