

Note: This document has not been finalised.
LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com;cs-a@lkkauto.com;admin-a@lkkauto.com

To: ECICS Limited
10 Eunos Road 8
#09-04A Singapore Post Centre
Singapore 408600

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Sharon Tan Chow Yen

Date: 05 Dec 2024

Preliminary Advice

Vehicle No	: SMN1974E	Accident Date	: 24/11/2024
Make	: BMW X3 XDRIVE30I	Policy No.	: MPC24P00285500
Assignment Date	: 27/11/2024	Excess	: S\$0.00
Date of Inspection	: 27/11/2024	Est. Duration of Repair	: 4
Inspection At	: CYS AUTOMOBILE SERVICES PTE LTD (WOODLANDS) 38 WOODLANDS INDUSTRIAL PARK EAST 1, #07-17, ADMIRALTY INDUSTRIAL PARK SINGAPORE 757700		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

RePAIRer's Estimate (Gross)	:S\$	27,484.50
Revised Amount	:S\$	16,196.50
Check Items (Estimated)	:S\$	0.00
Total	:S\$	16,196.50
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	120,000.00
COE / PARF Rebate	:S\$	68,625.00
Salvage Value	:S\$	
Margin for Repair	:S\$	51,375.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : KINDLY APPROVE ON CHECK ITEMS.