



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No.
19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MS LIBERTY INSURANCE PTE LTD	Ref:	CS/LIP24110563/Knh3e2
ONE RAFFLES QUAY #25-01 NORTH TOWER	Date:	19/12/2024
SINGAPORE 048583	Code:	LIP

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SLF 9639A	Veh. Inspected	SMF 8214L
Policy No.	-	Coverage	0
Claim No.	IVS24/2207	Excess	\$0.00
Assign From	CMPY	Assign Date	26/11/2024

2. Vehicle Details

Make & Model	TOYOTA HARRIER (A)	C.C	1998
Engine No.	8ARZ129356	Year of Reg.	27/11/2018
Chassis No.	JTEKB3GH40J002517	Colour	METALLIC BLACK
Odometer	106275 KM	Steering	IN ORDER
Brakes	IN ORDER	General	GOOD
Modification(s)	RIMS: STANDARD ALLOY RIM		

3. Conditions of Tyres

	Size	Make	Balance (mm)
R/H Front Tyre	235/55R18	YOKOHAMA	9
L/H Front Tyre	235/55R18	YOKOHAMA	9
R/H Rear Tyre	235/55R18	YOKOHAMA	9
L/H Rear Tyre	235/55R18	YOKOHAMA	9

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	26/11/2024	Inspection Date	27/11/2024
Survey held at	CHOON HOCK MOTOR TRADING CO - BLK 176 SIN MING DRIVE #05-05 SINGAPORE 575721		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days