

# CHOON HOCK MOTOR TRADING CO

26 November 2024

*Not Notified  
11 Rm 83250h  
Murray After Painting  
4 days*

## ESTIMATE REPAIR BILL ON SMF8214L TOYOTA HARRIER AUTO

|                                     |           |             |   |
|-------------------------------------|-----------|-------------|---|
| 1 pce rear tailgate                 | <i>Bu</i> | \$ 2,427.00 | ✓ |
| 1 pce rear tailgate "HARRIER" plate | <i>Pl</i> | \$ 85.00    | — |
| 1 pce rear tailgate "TURBO" plate   | <i>Pl</i> | \$ 85.00    | — |
| 1 pce rear bumper                   | <i>Bu</i> | \$ 924.10   | ✓ |
| 1 pce rear bumper reinforcement     | <i>Re</i> | \$ 580.00   | X |
| 1 pce rear bumper lower spoiler     | <i>Sp</i> | \$ 479.60   | ✓ |
| 1 pce rear bumper sensor            | <i>S</i>  | \$ 220.00   | X |
|                                     |           | \$ 4,800.70 |   |
|                                     | <i>25</i> |             |   |
| less 20%                            |           | \$ 960.15   |   |
|                                     |           | \$ 3,840.55 |   |

## LABOUR

|                                     |            |              |
|-------------------------------------|------------|--------------|
| Remove and refit tailgate           | \$ 150.00  | <i>60l</i>   |
| Remove and refit rear windscreen    | \$ 220.00  | <i>120l</i>  |
| 1 set windscreen sealant            | \$ 80.00   | <i>400ln</i> |
| Remove and refit rear bumper sensor | \$ 120.00  | <i>30l</i>   |
| Panel beating                       | \$ 800.00  | <i>400l</i>  |
| Spray painting                      | \$ 800.00  | <i>400l</i>  |
| Rustproofing                        | \$ 120.00  | <i>30l</i>   |
| Total amount :                      | \$6,130.55 | NETT         |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

Mailing address : 28 Surrey Road #18-03 Singapore 307762 Reg No: 30568200L  
Tel: (65) 64530778 Email: choonhockmotor@gmail.com