



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933  
TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO SNL 5332E

REPLACEMENT OF PARTS				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	TAILLAMP RH	CUT	\$556.00	\$556.00
1	REAR FENDER RH	TO REPAIR SEE LABOUR	\$940.00	\$0.00
1	REAR FENDER GLASS WITH MIDG RH	NOT NECESSARY	\$450.60	\$0.00
1	REAR BUMPER ASSY	BUCKLED/CRACKED	\$595.00	\$595.00
1	REAR BUMPER REFLECTOR RH	CRACKED	\$72.10	\$72.10
1	REAR BUMPER RETAINER WHITE	CRACKED	\$108.20	\$108.20
1	REAR BUMPER RETAINER BLACK	CRACKED	\$192.60	\$192.60
	<b>LESS 0.00 / 25.00% DISCOUNT</b>		\$0.00	(\$380.98)
			\$2,914.50	\$1,142.92

Special Nett				
Qty	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
1	REAR BUMPER CLIPS (SN)	NECESSARY	\$50.00	\$50.00
1	REAR FENDER GLASS SEALANT (SN)	NOT NECESSARY	\$80.00	\$0.00
			\$130.00	\$50.00

Labour				
	Description of Parts	Condition	Workshop Estimate (\$)	Our Adjusted (\$)
	TO CUT / WELD AND REMOVE AND REFIT DAMAGED PARTS. INCLUSIVE OF THE REPAIR OF REAR FENDER RH		\$700.00	\$400.00
	TO SPRAY PAINT ON AFFECTED PARTS		\$800.00	\$400.00
	TO REMOVE AND REFIT REAR REVERSE SENSOR		\$120.00	\$50.00
	TO REMOVE AND REFIT REAR GARNISHES AND ETC	NOT NECESSARY	\$200.00	\$0.00
	TUFF COAT ON AFFECTED PARTS	NOT NECESSARY	\$100.00	\$0.00
	TO CHECK WIRING		\$80.00	\$20.00
	TO REMOVE AND REFIT REAR FENDER GLASS	NOT NECESSARY	\$200.00	\$0.00
			\$2,200.00	\$870.00

<b>GRAND TOTAL</b>	<b>\$5,244.50</b>	<b>\$2,062.92</b>
--------------------	-------------------	-------------------

<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>		<b>\$1,550.00</b>
---	--	-------------------

Report Ref No: CS/LIP24110564/Knh3e2

MARKET VALUE: \$32,000.00 (EST)-LTA REIMBURSEMENT VALUE: \$21,330.00=NETT VALUE: \$10,670.00



## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park,  
Singapore 408933

TEL: 6256 3561 FAX: 6256 4315  
Reg. No: 199607198R GST Reg. No.  
19-9607198-R

## **KSC**

KENNETH KONG SENG CHEONG

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.